

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Iyor Li Shan (90092718)

not authorized

Accident Date : 04-Aug-22

Vehicle No : FBQ9256G (COE130130)

*Mercedes
12/8/22*

Vehicle Model : Honda
CB190SS ABS
Manual

Estimated Repair Costs

Qty	Description <u>List Items</u>		Amount S(\$)
		<i>2/c \$ 3700</i>	
		<i>4 days</i>	
1	Front fender	<i>R</i>	\$ 250.00 <i>X</i>
1	Front fender side cover - silver	<i>cu7</i>	\$ 165.00 <i>/</i>
1	Fork inner tubes - R/H	<i>sent/Dog</i>	\$ 520.00 <i>/</i>
1	Fork inner tubes - L/H	<i>n1</i>	\$ 520.00 <i>X</i>
1	Fork under bracket	<i>n1</i>	\$ 285.00 <i>X</i>
1	Handle-bar	<i>sent</i>	\$ 280.00 <i>/</i>
1	Handle-bar ends (1 set) <i>ols</i>	<i>scr</i>	\$ 120.00 <i>/</i>
1	Hand-grip (1 set)	<i>n1</i>	\$ 80.00 <i>X</i>
1	Headlamp (LED)	<i>one</i>	\$ 980.00 <i>/</i>
1	Meter assy	<i>one</i>	\$ 760.00 <i>/</i>
1	Throttle cable	<i>cu7</i>	\$ 205.00 <i>/</i>
2	Side mirrors <i>ols</i>	<i>cu7</i>	\$ 60.00 <i>1pc</i>
1	Brake lever	<i>scr</i>	\$ 82.00 <i>/</i>
1	Front signals	<i>cu7</i>	\$ 115.00 <i>/</i>
1	Fuel tank lower cover (silver)	<i>cu7</i>	\$ 180.00 <i>/</i>
2	Front footrests	<i>ols cu7</i>	\$ 75.00 <i>1pc</i>
2	Front footrest bracket	<i>ols one</i>	\$ 130.00 <i>1pc</i>
1	Brake pedal	<i>sent</i>	\$ 120.00 <i>/</i>
1	Exhaust assy	<i>cu7/Dog</i>	\$ 950.00 <i>/</i>
1	Exhaust protector	<i>cu7</i>	\$ 80.00 <i>/</i>
			\$ 6,537.00
		Less 10%	\$ 653.70
			\$ 5,883.30

Special Net Items

1	Number plate (1 set) <i>sent</i>	<i>scr</i>	\$ 38.00 <i>10</i>
2	Fork oils	<i>ols/scr</i>	\$ 30.00 <i>15</i>
2	Fork oil seals	<i>ols/scr</i>	\$ 56.00 <i>28</i>
1	Steering cone (1 set)	<i>n1</i>	\$ 150.00 <i>X</i>
1	Rear box	<i>cu7</i>	\$ 420.00 <i>300</i>
1	Rear box bracket	<i>n1</i>	\$ 180.00 <i>X</i>
			\$ 874.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Iyor Li Shan (90092718)

Accident Date : 04-Aug-22


Vehicle No : FBQ9256G (COE130130)

Honda
Vehicle Model : CB190SS ABS
Manual

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service (LOD) S\$70.00	\$	-
2	To check wiring and reset headlamp focusing	\$	17 80.00 X
3	To repair body frame	\$	17 480.00 X
4	To provide labour	\$	450.00 300
		\$	1,010.00
	Grand Total	\$	7,767.30

Singapore Dollars: Seven Thousand Seven Hundred Sixty-Seven and Cents: Thirty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4528
102
4075.2
353
300
4728.2