



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD  
#09-01 SINGAPORE 068897

Ref: CS3/AIS22007671/Gqy3

Date: 12/08/2022

Code: AIS

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMR 460G	Veh. Inspected	SJX 6515Y
Policy No.		Coverage (\$)	0.00
Claim No.	2022 22006025SL	Excess (\$)	0.00
Assign From	SHANTI	Assign Date	12/08/2022

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

Accident Date	06/08/2022	Inspection Date	12/08/2022
Survey held at	2 KAKI BUKIT AVENUE 2 ,#02-31 KAKI BUKIT AUTOHUB		
Repairer	CHENG CHUAN MOTOR SERVICES		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.