



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO22007672/Ecy3q2 Date: 06/10/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLC 3094B	Veh. Inspected	SMM 1192A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2202731/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	12/08/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA HRV	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHMRU1830JX201795	Colour	BROWN
Odometer	61735 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	DUNLOP	5 mm
L/H Front Tyre	205/65 R16	DUNLOP	5 mm
R/H Rear Tyre	205/65 R16	DUNLOP	5 mm
L/H Rear Tyre	205/65 R16	DUNLOP	5 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	27/07/2022	Inspection Date	29/08/2022
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days