



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0676/2022/EQ  
**DATE** : 11-Aug-22  
**WIP** : 36771

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/08/2022**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

**OWNER'S NAME** : MR VINCENT TAN KHAR KHENG  
**ADDRESS** : BLK 7 PASIR RIS DRIVE 4  
#07-05  
SINGAPORE 519459  
**TELEPHONE** : HP +65 83688688  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2100488648-05  
**VEHICLE NO** : **SJL 3700 L**  
**MODEL CODE** : A4 SEDAN 1.4 TFSI  
**MODEL YEAR** : 28/10/2016  
**ENGINE NO** : CVN 017632  
**CHASSIS NO** : WAUZZZF42HA027053  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 10-Aug-22  
**PLACE OF ACCIDENT** : JUNCTION OF LOYANG AVENUE AND  
TAMPINES ROAD



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJL 3700 L.**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	460.00 /	
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	700.00 /	
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	500.00 /	
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	300.00 150	
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,500.00 /	(phi)
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 3,460.00</b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJL 3700 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,500.00	✓ (photo)
7	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 450.00	280
8	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT.	S/N \$ 1,800.00	✓ (photo)
9	TO REMOVE AND RENEW ROODTOP LINER, PILLAR TRIMS AND CUSHION AIRBAGS.	S/N \$ 2,400.00	✓
10	TO REMOVE AND RENEW LEATHER SEAT CUSHION.	S/N \$ 780.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 6,930.00</b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJL 3700 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER AND RHS C-PILLAR REINFORCEMENT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,000.00	3500
12	TO RESPRAY REAR BUMPER, RHS REAR DOOR, DOOR HANDLE, RHS REAR FENDER, RHS C-PILLAR REINFORCEMENT, ROOF CHANNEL, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$ 7,000.00	3125
13	TO RENEW RHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	? (phh)
14	TO RENEW RHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 620.00	370
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 384 292.00	/
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 28,702.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJL 3700 L**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER / CR4	1	S	2,609.00
2	REAR BUMPER FIXING PARTS X	1	S	480.00
3	REAR BUMPER SECURING STRIP X	1	S	249.00
4	REAR BUMER SPOILER X	1	S	276.00
5	REAR BUMPER REFLECTOR - RH X	1	S	46.00
6	REAR OUTER TAIL LIGHT - RH X	1	S	1,135.00
7	REAR BUMPER GUIDE SECTION - LH / RH ?	2	S	52.00
8	REAR BUMPER LOWER GUIDE PIN ?	1	S	3.00
9	REAR BUMPER GUIDE SECTION - RH ?	1	S	51.00
10	REAR SIDE PANEL - RH / DP	1	S	4,357.00
11	GROMMET / ne	1	S	2.00
12	BLIND RIVET STUD / ne	1	S	10.00
13	REAR WINDOW / ne	1	S	1,287.00
14	REAR SIDE WINDOW - RH / ne	1	S	685.00
15	WINDOW PRIMER / ne	2	S	44.00
16	FUEL FLAP TANK CAP ?	1	S	100.00
17	REAR WHEEL HOUSING LINER - RH ?	1	S	260.00
18	C-PILLAR REINFORCEMENT LOWER - RH ?	1	S	220.00
19	REAR DOOR / DP	1	S	3,431.00
20	BUNGS / ne	1	S	5.00
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 15,302.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJL 3700 L**

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR OUTER DOOR SEAL - RH <i>rc</i>	1	\$	229.00
22	BONDING AGENT <i>rc</i>	1	\$	51.00
23	CLEANING SOLUTION <i>rc</i>	1	\$	74.00
24	APPLICATOR <i>rc</i>	1	\$	9.00
25	BUNGS <i>rc</i>	1	\$	5.00
26	REAR SEALING STRIP <i>?</i>	1	\$	19.00
27	REAR DOOR ATTACHMENT PARTS <i>?</i>	1	\$	943.00
28	REAR DOOR CATCH - RH <i>?</i>	1	\$	134.00
29	REAR DOOR SEAL - INNER <i>AV</i>	1	\$	247.00
30	REAR WINDOW REGULATOR - RH <i>?</i>	1	\$	305.00
31	REAR DOOR HANDLE EXTERIOR COVER - RH <i>?</i>	1	\$	98.00
32	REAR DOOR HANDLE OUTER HOUSING - RH <i>MIS</i>	1	\$	9.00
33	REAR DOOR HANDLE TRANSPARENT COVER - RH <i>MIS</i>	1	\$	7.00
34	REAR DOOR HANDLE SENSOR - RH <i>?</i>	1	\$	255.00
35	REAR DOOR EXTERIOR HANDLE <i>?</i>	1	\$	47.00
36	REAR DOOR HANDLE UNDERLAY - RH FRONT / REAR <i>?</i>	2	\$	8.00
37	REAR DOOR MOUNTING BAR - RH <i>?</i>	1	\$	183.00
38	REAR DOOR LOCK - RH <i>?</i>	1	\$	630.00
39	REAR DOOR LOCK STRIKER <i>?</i>	1	\$	77.00
40	REAR ALUMINIUM RIM - RH <i>rc</i>	1	\$	1,020.00
<b>SUB TOTAL SPARE PARTS</b>			<b>\$</b>	<b>4,350.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJL 3700 L**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	RUBBER VALVE / <i>MC</i>	1	\$	4.00	
42	REAR SUSPENSION CROSS MEMBER ?	1	\$	3,643.00	
43	WISHBONE - LOWER ARM ?	1	\$	963.00	
44	WISHBONE LINK - FRONT UPPER RH ?	1	\$	624.00	
45	WISHBONE LINK - FRONT RH ?	1	\$	137.00	
46	WISHBONE LINK - RH REAR UPPER ?	1	\$	501.00	
47	TRACK ROD - RH REAR LOWER ?	1	\$	188.00	
48	REAR WHEEL BEARING HOUSING - RH ?	1	\$	1,097.00	
49	RERA BEARING WHEELHUB ?	1	\$	723.00	
50	STONE CHIP GUARD ?	1	\$	49.00	
51	GAS SHOCK ADSORBER ?	1	\$	332.00	
52	ANTI-ROLL BAR ?	1	\$	456.00	
53	COUPLING ROD ?	1	\$	94.00	
54	AIRBAG HEAD UNIT - LH / RH ? - <i>BR</i>	(2)	\$	4,138.00	
55	AIRBAG SIDE UNIT / <i>MC (sent RH)</i>	1	\$	1,688.00	
56	AIRBAG CONTROL UNIT - <i>MC</i>	1	\$	2,364.00	
57	REAR AIRBAG CRASH SENSOR - <i>MC</i>	1	\$	486.00	
58	CENTRAL PROTECTION - <i>MC (cable)</i>	1	\$	590.00	
59	THREE-POINT SEAT BELT - <i>joint</i>	(2)	\$	2,454.00	
60	SEAT BELT HEIGHT ADJUSTER - LH / RH ?	2	\$	384.00	
<b>SUB TOTAL SPARE PARTS</b>			:	<b>\$ 20,915.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJL 3700 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	HEADLINING MOULDED CLOTH / CRU	1	\$	2,168.00
62	BACKREST COVER - RH (Seat Cover RH) - TN	1	\$	2,708.00
63	FOLDING GRAB HANDLE ?	2	\$	326.00
64	FOLDING GRAB HANDLE ?	2	\$	326.00
65	A-PILLAR TRIM / CR4	(2)	\$	458.00
66	B-PILLAR UPPER TRIM - LH / RH ?	2	\$	520.00
67	C-PILLAR TRIM - LH / RH ?	2	\$	508.00
68	D-PILLAR TRIM - LH / RH ?	2	\$	508.00
69	REAR WINDSCREEN SEALANT / N/A	S/N	\$	200.00
70	SUNDRIES ?		\$	500.00
<b>TOTAL SPARE PARTS</b>			:	<b>\$ 48,789.00</b>
<b>TOTAL LABOUR CHARGES</b>			:	<b>\$ 28,702.00</b>
<b>GRAND TOTAL</b>			:	<b>\$ 77,491.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Stew (LKK)  
12/8/22, 10.00am

OD-MAL  
EXC - ?  
PIP  
21 dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT