

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 17 Oct 2022

Preliminary Advice

| | | | |
|--------------------|--------------------------|-------------------------|----------------------|
| Vehicle No | : SLR8989H | Accident Date | : 02/08/2022 |
| Make | : BMW 218I | Policy No. | : DMPCSNW00257432100 |
| Assignment Date | : 12/08/2022 | Excess | : S\$500.00 |
| Date of Inspection | : 17/10/2022 | Est. Duration of Repair | : 4 |
| Inspection At | : PERFORMANCE MOTORS LTD | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 11,237.50 |
| Revised Amount | :S\$ | 7,418.60 |
| Check Items (Estimated) | :S\$ | 398.35 |
| Total | :S\$ | 7,816.95 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|------------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 165,000.00 |
| COE / PARF Rebate | :S\$ | 87,332.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 77,668.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : .Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .