

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 62884 Page No. : 1 of 5
Date Estimated : 12/08/2022
Prepared By : Jack Ng Guo Ming

| | |
|--|--|
| <p>- ESTIMATE REPAIR FOR - Daniel Seah 100 Gerald Drive #01-84 Singapore 798592</p> | <p>- ACCOUNT - 135 China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909</p> |
|--|--|

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-----------------|---------|
| SLR8989H | WBA12AK0207H36866 | 29/09/2021 | 218i Gran Coupe | 15 |

| DESCRIPTION | VALUE |
|--|-----------------|
| To replace front bumper and front left fender. | 1275 2,250.00 |
| To respray front bumper and left front fender. | 1826 1,923.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function. | 168 177.00 |
| To check electrical wiring system and lighting | 168 177.00 |
| To replace left headlight. | 456 481.00 |
| To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x). | X 531.00 |
| To replace tyre and wheel rim including balancing. (1x). | X 94.00 |
| Sundries. | 150.00 |
| Total Labour 1: | 5,783.00 |

| DESCRIPTION | QTY | PRIC | VALUE |
|--|-----|----------|-----------------|
| ALLOY RIM 7.5JX17 DOUBLE SPK 548 X | 1 | 996.90 | 996.90 |
| FRT LH SIDE PANEL X R | 1 | 639.70 | 639.70 |
| LH FOG LAMP COVER / CUT (Black) | 1 | 47.30 | 47.30 |
| FRT BUMPER BOTTOM TRIM PANEL ? | 1 | 177.00 | 177.00 |
| LH AIR INLET FINISHER ? | 1 | 68.95 | 68.95 |
| LH GRID LATERAL ? | 1 | 80.80 | 80.80 |
| FRT FLAP TOWING EYE PRIMED X | 1 | 43.95 | 43.95 |
| FRT BUMPER PANEL PRIMED (PDC/PMA) / DO | 1 | 929.20 | 929.20 |
| SET MOUNTING PDC/PMA SENSOR FRT ? | 1 | 71.60 | 71.60 |
| LH HEADLIGHT LED TECHNOLOGY / CUT | 1 | 2,399.10 | 2,399.10 |
| Total Parts : | | | 5,454.50 |

ser

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 430180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

| | | |
|----------------|--------------------|-------------------|
| Estimate No. | : b1 62884 | Page No. : 2 of 5 |
| Date Estimated | : 12/08/2022 | |
| Prepared By | : Jack Ng Guo Ming | |

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-----------------|---------|
| SLR8989H | WBA12AK0207H36866 | 29/09/2021 | 218i Gran Coupe | 15 |

Steve (LKK)
17/10/22, 11.30am
M R
PIP
by BL by
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

| | | | |
|-------------|----------------|------------------|----------|
| | Labour 1 | : | 5,783.00 |
| | Parts | : | 5,454.50 |
| | Labour 2 | : | 0.00 |
| | Excess | : | 0.00 |
| | Total GST @ 7% | : | 786.63 |
| Grand Total | : | <u>12,024.13</u> | |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **