


Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721
 Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: admin@fulcoautocare.com

Make/Model: CITROEN BERLINGO
 Engine/Chassis No.: VF77FBHYMHJ758457
 Date of accident:
 Damaged area: O/S Front

Date: 11/08/2022
 Claim Type: OD
 VRN: GBH2141Y



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet	1	\$ 945.30	\$ 945.30
2	Bonnet rubber seal	1	\$ 55.00	\$ 55.00
3	Bonnet lock	1	\$ 238.00	\$ 238.00
4	Bonnet hinge	2	\$ 112.00	\$ 224.00
5	Front grille top panel	1	\$ 560.00	\$ 560.00
6	Front grille chrome garnish	1	\$ 368.00	\$ 368.00
7	Front bumper	1	\$ 886.00	\$ 886.00
8	Front bumper bracket	2	\$ 146.00	\$ 292.00
9	Front bumper side retainer	2	\$ 109.00	\$ 218.00
10	Front bumper reinforcement	1	\$ 465.00	\$ 465.00
11	Front bumper inner sponge	1	\$ 248.00	\$ 248.00
12	Front bumper foglamp o/s	1	\$ 361.00	\$ 361.00
13	Front bumper foglamp garnish o/s	1	\$ 278.00	\$ 278.00
14	Front bumper tow cover	1	\$ 38.00	\$ 38.00
15	Front bumper lower cover	1	\$ 266.00	\$ 266.00
16	Aircon condenser	1	\$ 1,287.00	\$ 1,287.00
17	Headlamp o/s	1	\$ 1,594.00	\$ 1,594.00
18	Front fender o/s	1	\$ 731.00	\$ 731.00
19	Front fender inner shield o/s	1	\$ 221.00	\$ 221.00
20	Front bumper lower grille	1	\$ 388.00	\$ 388.00
21	Day running lamp o/s	1	\$ 298.00	\$ 298.00
22	Front lower arm o/s	1	\$ 398.00	\$ 398.00
23	Front shock absorber o/s	1	\$ 492.00	\$ 492.00
24	Front shock absorber top mount o/s	1	\$ 112.00	\$ 112.00
25	Front shock absorber top mount bearing o/s	1	\$ 42.00	\$ 42.00
26	Front end link o/s	1	\$ 105.00	\$ 105.00
27	Tie rod end o/s	1	\$ 136.00	\$ 136.00
28	Front wheel knuckle o/s	1	\$ 419.00	\$ 419.00
29	Front wheel knuckle bearing o/s	1	\$ 184.00	\$ 184.00
30	Steering rack & pinion assy	1	\$ 1,993.00	\$ 1,993.00

Repair Estimate

31	Front cross member	1	\$ 994.00	\$ 994.00
			Subtotal	\$ 14,836.30
			List discount	10.00%
			Total	\$ 13,352.67

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet insulator clips	8	\$ 5.50	\$ 44.00
2	Bonnet rubber seal clips	4	\$ 3.50	\$ 14.00
3	Front bumper clips	10	\$ 5.50	\$ 55.00
4	Front fender inner shield o/s clips	8	\$ 5.50	\$ 44.00
5	Front bumper lower cover clips	10	\$ 5.50	\$ 55.00
6	Front bumper sensor o/s	1	\$ 263.00	\$ 263.00
7	Front steel wheel o/s	1	\$ 350.00	\$ 350.00
8	Front wheel cover o/s	1	\$ 160.00	\$ 160.00
9	Front tyre o/s	1	\$ 150.00	\$ 150.00
10	Sundries	1	\$ 50.00	\$ 50.00
			Total	\$ 1,185.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and replace a/c condenser to facilitate repair work. To recharge system and check a/c functionality.	0.75	\$ 150.00
4	To remove and refit o/s front rim & tyre for replacement. To perform tyre balancing.	0.25	\$ 50.00
5	Supply spray paint material and necessary items to respray affected area / panel.	4	\$ 800.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
7	To remove and refit o/s front undercarriage for replacement of parts.	1	\$ 200.00
8	To conduct computerized wheel alignment.	0.5	\$ 100.00
		Total labour	\$ 2,450.00

Estimate Grand Total		\$ 16,987.67
-----------------------------	--	---------------------