

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref	CS/ASM22007685/Kny3m4	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date	e: 22/08/2022	
	ATTN: KHOR SAW	/ THENG	Cod	e: ASM	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6821R	Veh. Inspected	SKS 5331G	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S2M048SE	Excess (\$)	0.00	
	Assign From	KHOR SAW THENG	Assign Date	12/08/2022	
2.	. Vehicle Particulars & Condition				
	Make & Model	MERCEDES A180 (A)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	WDD1760422J363014	Colour	METALLIC GREY	
	Odometer	142595 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	PIRELLI	8 mm	
	L/H Front Tyre	225/45 R17	PIRELLI	8 mm	
	R/H Rear Tyre	225/45 R17	PIRELLI	8 mm	
	L/H Rear Tyre	225/45 R17	PIRELLI	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/08/2022	Inspection Date	16/08/2022	
	Survey held at	READY AUTO CARE PL	•		
		BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE 568047			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	2 W	orking Days	