

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
Tel : 64810304 Fax : 64815587 Reg No : 200600989K

MSIG Insurance (Singapore) Pte Ltd (SGX Centre)

Estimate Repair

Motorcar Claim Department

Attn: Claim Officer

Date : 16/8/2022

Accident Involving SKS5331G & SH6821R On 11/8/2022

Item	Descriptions	Amount
1	Rear Bumper <i>1421-50</i>	<i>Br/nd</i> \$ 1,985.00 ✓
<i>10{</i> Total For Parts		<u>\$ 1,985.00</u>

S/N Item (s)

1	Rear Bumper Clips - 1 Set	<i>na</i> \$ 35.00 ✓
Total For S/N		<u>\$ 35.00</u>

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	
	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 300.00 <i>2201</i>
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 350.00 <i>2501</i>
3	Computer Diagnose To Reset Parking Sensor False Memory	\$ 120.00 <i>601</i>
4	Check Wiring, Lighting System For Proper Function	\$ <i>na</i> 50.00 <i>x</i>
		<u>\$ 820.00</u>

Ready Auto Care Pte Ltd

Total For Parts & Labour \$ 2,840.00

No Of Days For Repair 3 Days

Not Authorized
11 Sep 8145 dr
Primary After Pain
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: