

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 11.08.2022

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBG5904Z**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 01.08.2022
TIME OF ACCIDENT : 16:40 HRS

RDH201 2230635

Celine

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SLIDING DOOR LH <i>Distorted</i>	1	\$ 1,650.00	\$ 1,650.00
2	SLIDING DOOR SWITCH CONNECTOR <i>new</i>	1	\$ 88.00	\$ 88.00
3	SLIDING DOOR STEP PANEL RH <i>new</i>	1	\$ 817.00	\$ 817.00
4	SLIDING DOOR LOWER RAILWAY PANEL LH	1	\$ 946.00	\$ 946.00
5	SLIDING DOOR ROLLER (LOWER) LH <i>Top new</i>	1	\$ 317.00	\$ 317.00
6	SLIDING DOOR LOCK CATCHER LH <i>new</i>	1	\$ 26.00	\$ 26.00
7	SLIDING DOOR INNER LOCK LH <i>new</i>	1	\$ 522.00	\$ 522.00
8	SLIDING DOOR STOPPER (SET) <i>new</i>	2	\$ 27.00	\$ 54.00
9	SLIDING DOOR FRAME WEATHER STRIP LH <i>new</i>	1	\$ 331.00	\$ 331.00
10	SLIDING DOOR INNER BOARD LH <i>new</i>	1	\$ 325.00	\$ 325.00
11	REAR SIDE PANEL LH <i>new</i>	1	\$ 1,848.00	\$ 1,848.00
12	REAR SHOCK ABSORBER LH	1	\$ 439.00	\$ 439.00
13	REAR WHEEL HUP LH	1	\$ 390.00	\$ 390.00
14	REAR WHEEL HUP BEARING LH	1	\$ 187.00	\$ 187.00
15	REAR WHEEL CAP LH	1	\$ 258.30	\$ 258.30

TOTAL PRICE \$ 8,198.30
LESS 25% \$ 2,049.58
SUB TOTAL PRICE \$ 6,148.73

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SLIDING DOOR INNER BOARD CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	SLIDING DOOR GLASS SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00
3	SLIDING DOOR GLASS INNER SEAL LH <i>new</i>	1	\$ 60.00	\$ 60.00
4	REAR SIDE PANEL SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00
5	SIDE PANEL GLASS SEALANT INNER SEAL LH <i>new</i>	1	\$ 120.00	\$ 120.00
6	SIDE PANEL GLASS SEALANT LH <i>new</i>	1	\$ 120.00	\$ 120.00
7	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>new</i>	1	\$ 1,500.00	\$ 1,500.00

TOTAL \$ 2,010.00

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBG5904Z**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 01.08.2022
 TIME OF ACCIDENT : 16:40 HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	250
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	400
3	TUFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	X
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
7	TRANSFER SLIDING DOOR MECHANISM RH	\$ 80.00	✓
8	REMOVE AND REFIX SLIDING DOOR GLASS RH	\$ 100.00	50
9	REMOVE AND REFIX REAR SIDE PANEL RAILWAY RH	\$ 80.00	X
10	REMOVE AND REFIX REAR SIDE PANEL GLASS RH	\$ 100.00	X
11	REMOVE AND REFIX REAR WHEEL BEARING	\$ 60.00	X
12	FOUR WHEEL ALIGNMENT	\$ 120.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$4,980.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,158.73
 TOTAL LABOUR COST : \$ 4,980.00
 TOTAL REPAIR COST : \$ 13,138.73

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian L
 12/12/22
 03 Days

total: 3084.75

h/s: 241c

840