

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007693/KVY3M4**Date:** 24/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00088782201

**Claimant Vehicle
No :** SLC9810L**Insured Vehicle
No :** SLH9634C

Date of Loss: 08/08/2022

Nature of Claim: TP

Claim
No: SNM22D205616/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLC9810L**

Make & Model: KIA FORTE K3, 1.6 EX (A)

Engine No: G4FGGH612316

Reg. Date: 31/05/2016 (Man. Year: 2016)

Chassis No: KNAFX411MG5596348

Colour: Metallic Grey

Odometer: 110080 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,322.00	2,342.40	1,979.60	45.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,060.00	1,100.00	50.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,482.00	3,402.40	3,079.60	47.51
Approved Total (Overridden) (\$\$)		2,700.00		
Nett Amount (\$\$)	6,482.00	2,700.00	3,782.00	58.35

INSPECTION

Date of Assignment: 16/08/2022

Date Inspected: 15/08/2022 Inspected At:

Poon Siang Seow (HQ)
160 Sin Ming Drive, #05-13 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2022)
Parts:	143	KIA FORTE K3 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9810L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Bent	1,284.00 F	*1,284.00 FL
2	1		*ROCKER PANEL	Bent	1,864.00 F	*1,253.00 FL
3	1		*FRONT DOOR HINGE x2	Repair	120.00 F	*- FL
4	1		*FRONT DOOR STICKER x2	Necessary	65.00 F	*65.00 FL
5	1		*FRONT DOOR POWER MOTOR AND GEAR	Distorted/Jammed	560.00 F	*326.00 FL
6	1		*FRONT DOOR OUTER MOULDING	Serviceable	150.00 F	*- FL
7	1		*FRONT DOOR LOCK	Repair	279.00 F	*- FL
Sub Total (\$\$)						4,322.00 2,928.00
- List Item Discount on L Items 0.00/20.00% (\$\$)						0.00 585.60
Total Parts (\$\$)						4,322.00 2,342.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	80.00	60.00
2	PANEL BEATING	New	1,200.00	600.00
3	SPRAY PAINTING	New	880.00	400.00
Gross Labour Cost (\$\$)			2,160.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >