

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0693/2022/EQ  
**DATE** : 15-Aug-22  
**WIP** :

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/08/2022**

**YOUR INSURED VEH NO : SMB 77 P**

**STRIDES AUTOMOTIVE SERVICES Pte Ltd**  
60 WOODLANDS INDUSTRIAL PARK E4  
SINGAPORE 757705  
Attn : Motor Claims Dept  
**Tel: 6866 2615 - Fax: 6368 7421**

Hi Adrian,

6 days - ok - Jy - 1 Mar 23

**OWNER'S NAME** : TERASAKI ELECTRIC COMPANY (FAR EAST) PTE LTD  
**ADDRESS** : BLK 2 HILLVIEW RISE  
#11-11  
SINGAPORE 667978  
**TELEPHONE** : HP +65 96816948  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 5103299131-03  
**VEHICLE NO** : **SKP 6512 K**  
**MODEL CODE** : TOYOTA COROLLA ALTISD 1.6L  
**MODEL YEAR** : YEAR 2014  
**ENGINE NO** : 1ZRX447266  
**CHASSIS NO** : MR053REH104516003  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 10-Aug-22  
**PLACE OF ACCIDENT** : BUKIT BATOK EAST AVE 2

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKP 6512 K**

| S/N                         | NATURE OF JOBS                                                                                                                                           |        | ESTIMATED<br>CHARGES |           | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-----------|-------------------------------|
| 1                           | TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSCPECT FOR DAMAGES.                              | S/N \$ | 400.00               | \$        | 200.00                        |
| 2                           | TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 1,500.00             | \$        | 700.00                        |
| 3                           | TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS SILL PANEL, DOOR HANDLE, DOOR HINGES AND LHR REAR FENDER.                                                  | \$     | 2,400.00             | \$        | 1,050.00                      |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                            | S/N \$ | 192.00               | \$        | 50.00                         |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                          | :      | <b>\$ 4,492.00</b>   | <b>\$</b> | <b>2,000.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKP 6512 K**
**DAMAGED PARTS & PRICES**

| S/N                         | PARTS DESCRIPTION                       | QTY | S/NETT      | REMARKS     |
|-----------------------------|-----------------------------------------|-----|-------------|-------------|
| 1                           | FRONT DOOR - LH                         | 1   | \$ 1,250.00 | \$ 937.50   |
| 2                           | FRONT DOOR WEATHER STRIP - LH           | 1   | \$ 188.00   |             |
| 3                           | FRONT DOOR INNER BLACK TAPE - LH        | 1   | \$ 63.00    | \$ 47.25    |
| 4                           | FRONT DOOR GLASS RUN - LH               | 1   | \$ 113.00   |             |
| 5                           | FRONT DOOR HOLE COVER - LH (PLASTIC)    | 1   | \$ 80.00    |             |
| 6                           | FRONT DOOR B-PILLAR TRIM (OUTSIDE) - LH | 1   | \$ 325.00   | \$ 243.75   |
| 7                           | REAR DOOR B-PILLAR TRIM (OUTSIDE) - LH  | 1   | \$ 450.00   | \$ 337.50   |
| 8                           | REAR DOOR - LH                          | 1   | \$ 1,250.00 | \$ 937.50   |
| 9                           | REAR DOOR WEATHER STRIP - LH            | 1   | \$ 200.00   |             |
| 10                          | REAR DOOR INNER BLACK TAPE - LH         | 1   | \$ 90.00    | \$ 67.50    |
| 11                          | REAR DOOR GLASS RUN - LH                | 1   | \$ 113.00   |             |
| 12                          | REAR DOOR HOLE COVER - LH (PLASTIC)     | 1   | \$ 80.00    |             |
| 13                          | REAR DOOR WINDOW REGULATOR - LH         | 1   | \$ 225.00   |             |
| 14                          | REAR DOOR WINDOW MOTOR - LH             | 1   | \$ 450.00   |             |
| 15                          | STONE CHIP                              | S/N | \$ 180.00   | \$ 180.00   |
| 16                          | SUNDRIES                                |     | \$ 350.00   |             |
| <b>TOTAL SPARE PARTS</b>    |                                         | :   | \$ 5,407.00 | \$ 2,751.00 |
| <b>TOTAL LABOUR CHARGES</b> |                                         | :   | \$ 4,492.00 | \$ 2,000.00 |
| <b>GRAND TOTAL</b>          |                                         | :   | \$ 9,899.00 | \$ 4,751.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-14/10/22