

# EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

VEHICLE NO : GBL2187U  
 MAKE & MODEL : TOYOTA HIACE VAN TURBO 5DR MT  
 CHASSIS NO : JTFHT02P700251657

DATE : 11 AUG 2022  
 CLAIM TYPE : TP CLAIM  
 D.O.A : 05 AUG 2022

TO : ALLIANZ

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER <i>441/60</i>		\$ 481.80	\$ <del>481.80</del> 481.80
2	2	REAR BUMPER RETAINER LH/RH		\$ 49.80	\$ <del>X NN</del> 99.60
3	2	REAR BUMPER UPPER COVER LH/RH		\$ 99.80	\$ <del>X NN</del> 199.60
4	2	REAR BUMPER UPPER COVER RETAINER LH/RH		\$ 52.90	\$ <del>X NN</del> 105.80
5	4	REAR BUMPER CENTER BRACKET <i>026</i>		\$ 47.70	\$ <del>X NN</del> 190.80
6	1	REAR WINDSCREEN GLASS <i>1191</i>		\$ <del>1191</del> 1,317.50	\$ <del>bno</del> 1,317.50
7	1	REAR END PANEL OUTER		\$ 363.70	\$ <del>RNN BT</del> 363.70
8	1	TAILGATE <i>2159</i>		\$ <del>2159</del> 2,293.20	\$ <del>bc</del> 2,293.20
9	1	TAILGATE LOCK <i>299.60</i>		\$ <del>299.60</del> 323.60	\$ <del>7 BT</del> 323.60
10	1	TAILGATE WEATHERSTRIP		\$ <del>433.30</del> 433.30	\$ <del>X NN</del> 433.30
11	1	TAILGATE GARNISH <i>151.20</i>	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	\$ 151.20	\$ <del>cut</del> 151.20
12	1	TAILGATE LOGO		\$ 72.20	\$ <del>net</del> 72.20
13	2	TAIL LAMP LH/RH		\$ 324.40	\$ <del>X NN</del> 648.80
14	1	THIRD BRAKE LIGHT		\$ 203.90	\$ <del>X NN</del> 203.90
15	1	REAR WIPER ARM		\$ 90.00	\$ <del>X NN</del> 90.00
16	1	REAR WIPER MOTOR ASSY		\$ 818.10	\$ <del>X NN</del> 818.10
17	1	REAR BOOT STEP PLATE		\$ 112.30	\$ <del>X NN</del> 112.30
				\$ 7,235.40	\$ 7,905.40
Acknowledged by Repairer Signature: <i>4718.50</i> Date: <i>3538.87</i>				TOTAL PRICE	\$ 7,905.40
				LESS 25%	\$ 1,976.35
				SUB TOTAL PRICE	\$ 5,929.05

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIP SET		\$ 50.00	\$ <del>30 net</del> 50.00
2	1	REVERSE SENSOR		\$ 200.00	\$ <del>NN</del> 200.00
3	1	70KM/H STICKER		\$ 30.00	\$ <del>NN</del> 30.00
4	1	SEALANT		\$ 80.00	\$ <del>NN</del> 80.00
5	1	REAR NO. PLATE		\$ 45.00	\$ <del>X NN</del> 45.00
6	1	PAN PACIFIC METAL PLATE		\$ 80.00	\$ <del>NN</del> 80.00
TOTAL S/NETT				\$ 485.00	\$ <del>350</del> 485.00

**Labour Charges**

1	To cut/weld, panel beat & align Rear portion, to remove & replace damaged parts.	\$ 1,200.00	<i>600</i>
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	<i>30</i>
3	To check and rectify lighting & wiring.	<i>3538.87</i>	<i>30</i>
4	To remove & replace reverse sensor.	<i>250</i>	<i>30</i>
5	To remove & refit spare tyre, interior trims to facilitate the repair.	<i>1780</i>	<i>60</i>
6	To putty, spray painting Rear Portions & other affected areas.	<i>5668.87</i>	<i>700</i>
7	To transfer tailgate components to new tailgate.	<i>61584.500</i>	<i>60</i>
8	To remove & refit rear windscreen glass.	<i>5 days</i>	<i>120</i>
9	To do artwork sticker on tailgate.	<i>350.00</i>	<i>150</i>
<i>Tan J M 97485749</i> <i>WP 12/8/22 @ 5 pm</i> <i>4/5 Resurvey after work</i>		<i>1780.</i>	<i>05 days</i>