

Vehicle Damage Assessment Report for [SDN8663M]

Estimate Created: 15/08/2022 04:19 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 19/04/2023 02:07 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Sienta
Engine Type			
License Plate Number	SDN8663M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	13,243.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$ 2,876.50 WITH 4 WORKING DAYS

Insurlogic 5 (19/04/2023 02:06)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BUMPER EXTENSION CENTER		1	277.50	0.00 %	277.50
REAR LID		1	1109.25	0.00 %	1,109.25
REAR LID LOGO		1	66.75	0.00 %	66.75
REAR LID EMBLEH SIENTA		1	66.75	0.00 %	66.75
REAR LID EMBLE "G"		1	45.00	0.00 %	45.00
REAR LID CHROME PROTECTOR		1	281.25	0.00 %	281.25

Parts Subtotal 1,846.50

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO REMOVE AND TRANSFERL REAR LID'S CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHT AND REAR LID WIPER ASSY	RnR	80.00	0.00 %	80.00
TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	RnR	120.00	0.00 %	120.00
TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	RnR	80.00	0.00 %	80.00
TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID RE-ORANIZE CRASH MANAGEMENR COMPONENTS REINSTALL ALL PARTS REMOVED	RnR	350.00	0.00 %	350.00
TO CARRY OUT DIAGNOSTIC CHECK	RnR	50.00	0.00 %	50.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO RESPARY REAR BUMPER AND REAR LID	Full spray	350.00	0.00 %	350.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 680.00

Paint Labor Subtotal 350.00

Labor Subtotal 1,030.00

Summary

Repair Cost 2,876.50

Discount(0 %) (0.00)

2,876.50

Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,876.50