

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0667/2022/EQ
DATE : 6-Aug-22
WIP : 36365

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/08/2022.

YOUR INSURED VEH NO : PC 6489 D

INDIA INTERNATIONAL INSURANCE PTE LTD

60 CECIL STREET

#04-#05 IOB BUILDING

SINGAPORE 049711

Attn: Motor Claims Dept

OWNER'S NAME : MR. TAN JOON MENG
ADDRESS : BLK 21 QUEEN'S CLOSE
#04-131
SINGAPORE 140021
TELEPHONE : HP +65 90676699
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10740254R00
VEHICLE NO : **SDN 8663 M**
MODEL CODE : TOYOTA SIENTA
MODEL YEAR : 12/6/2021
ENGINE NO : 2NRX696909
CHASSIS NO : MHFZ28H3900071474
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Aug-22
PLACE OF ACCIDENT : JURONG GATEWAY ROAD/
BOON LAY WAY CROSS JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDN 8663 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	
SUB-TOTAL LABOUR CHARGES		:	\$ 3,040.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDN 8663 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 1,200.00	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 4,432.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDN 8663 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,925.00	
2	REAR BUMPER SIDE RETAINER - LH / RH	2	\$ 250.00	
3	REAR BUMPER SIDE SUPPORT - LH / RH	2	\$ 250.00	
4	REAR BUMPER EXTENSION - CENTER	1	\$ 370.00	
5	REAR BUMPER EXTENSION - LH / RH	2	\$ 275.00	
6	REAR BUMPER REFLECTOR - LH / RH	2	\$ 219.00	
7	REAR BUMPER FOGLAMP	1	\$ 386.00	
8	REAR LID	1	\$ 1,479.00	
9	REAR LID WEATHER STRIP	1	\$ 495.00	
10	REAR LID LOGO	1	\$ 89.00	
11	REAR LID EMBLEM "SIENTA"	1	\$ 89.00	
12	REAR LID EMBLE "G"	1	\$ 60.00	
13	REAR LID LOCK ASSY	1	\$ 659.00	
14	REAR LID STRIKER ASSY	1	\$ 49.00	
15	REAR LID CHROME PROTECTOR	1	\$ 375.00	
16	REAR LID TOP LAMP	1	\$ 497.00	
17	REAR LID LAMP - LH / RH	2	\$ 396.00	
18	REAR WIPER ARM	1	\$ 127.00	
19	REAR WIPER MOTOR	1	\$ 927.00	
20	REAR WIPER	1	\$ 65.00	
21	TAIL LAMP - LH / RH	2	\$ 496.00	
22	CAR PLATE LIGHT - LH / RH	2	\$ 126.00	
23	REVERSE SENSOR	1	\$ 250.00	
24	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 10,154.00	
TOTAL LABOUR CHARGES		:	\$ 4,432.00	
GRAND TOTAL		:	\$ 14,586.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT