

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0667/2022/EQ
DATE : 6-Aug-22
WIP : 36365

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/08/2022.
YOUR INSURED VEH NO : PC 6489 D


INDIA INTERNATIONAL INSURANCE PTE LTD
60 CECIL STREET
#04-#05 IOB BUILDING
SINGAPORE 049711
Attn: Motor Claims Dept

OWNER'S NAME : MR. TAN JOON MENG
ADDRESS : BLK 21 QUEEN'S CLOSE
#04-131
SINGAPORE 140021
TELEPHONE : HP +65 90676699
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10740254R00
VEHICLE NO : SDN 8663 M
MODEL CODE : TOYOTA SIENTA
MODEL YEAR : 12/6/2021
ENGINE NO : 2NRX696909
CHASSIS NO : MHFZ28H3900071474
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Aug-22
PLACE OF ACCIDENT : JURONG GATEWAY ROAD/
BOON LAY WAY CROSS JUNCTION

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDN 8663 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$ 480.00	80 ✓
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00	120 ✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	X
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	80 ✓ 80.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	350 ✓
SUB-TOTAL LABOUR CHARGES		: \$ 3,040.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDN 8663 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 1,200.00	350 ✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	50 ✓
TOTAL LABOUR CHARGES		: \$ 4,432.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDN 8663 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER X NN	1	\$ 1,925.00	
2	REAR BUMPER SIDE RETAINER - LH / RH X NN	2	\$ 250.00	
3	REAR BUMPER SIDE SUPPORT - LH / RH X NN	2	\$ 250.00	
4	REAR BUMPER EXTENSION - CENTER / CM	1	\$ 370.00	277.50
5	REAR BUMPER EXTENSION - LH / RH X NN	2	\$ 275.00	
6	REAR BUMPER REFLECTOR - LH / RH X NN	2	\$ 219.00	
7	REAR BUMPER FOG LAMP X NN	1	\$ 386.00	
8	REAR LID / ON	1	\$ 1,479.00	1,109.25
9	REAR LID WEATHER STRIP X NN	1	\$ 495.00	
10	REAR LID LOGO / M	1	\$ 89.00	66.75
11	REAR LID EMBLEM "SIENTA" / M	1	\$ 89.00	66.75
12	REAR LID EMBLEM "G" / M	1	\$ 60.00	45.00
13	REAR LID LOCK ASSY X NN	1	\$ 659.00	
14	REAR LID STRIKER ASSY X NN	1	\$ 49.00	
15	REAR LID CHROME PROTECTOR / CM	1	\$ 375.00	281.25
16	REAR LID TOP LAMP X NN	1	\$ 497.00	
17	REAR LID LAMP - LH / RH X NN	2	\$ 396.00	
18	REAR WIPER ARM X NN	1	\$ 127.00	
19	REAR WIPER MOTOR ? X NN	1	\$ 927.00	
20	REAR WIPER X NN	1	\$ 65.00	
21	TAIL LAMP - LH / RH X NN	2	\$ 496.00	
22	CAR PLATE LIGHT - LH / RH X NN	2	\$ 126.00	
23	REVERSE SENSOR X NN	1	\$ 250.00	
24	SUNDRIES / M ? X NN		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 10,154.00	
TOTAL LABOUR CHARGES		:	\$ 4,432.00	
GRAND TOTAL		:	\$ 14,586.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

- 25% Part Discount
Pike check

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Stew (LKK)
11/8/22, 11:30am

m R
4 dys
PIP
M B y

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT