

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22007701/APA3Q2**Date:** 20/04/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0001657  
**Claimant Vehicle No :** SLS6939K **Insured Vehicle No :** FBT9005Z  
 Date of Loss: 05/08/2022 Nature of Claim: TP Claim No: MFL2022D0004333

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS6939K**  
 Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZ528874  
 Reg. Date: 30/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V5J1013403  
 Colour: Grey Odometer: 63390 km  
 Engine Capacity: 999 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,213.00	0.00	4,213.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,872.00	550.00	22.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,635.00</b>	<b>1,872.00</b>	<b>4,763.00</b>	<b>71.79</b>
<b>+ GST 8.00/8.00% (S\$)</b>	530.80	149.76	381.04	71.79
<b>Nett Amount (S\$)</b>	<b>7,165.80</b>	<b>2,021.76</b>	<b>5,144.04</b>	<b>71.79</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,209.21</b>		

INSPECTION

Date of Assignment: 12/08/2022  
 Date Inspected: 12/08/2022 Inspected At: Premium Automobiles Pte Ltd (HQ)  
 55 UBI ROAD 1  
 Singapore 408699  
 Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
<b>Parts:</b> 144	AUDI A3 999cc SEDAN TFSI S TRONIC (LED) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLS6939K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,317.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Not Necessary	264.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	36.00 FS	*- FS
4	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	642.00 FS	*- FS
5	2		*REAR BUMPER BRACKET -LH/RH	Not Necessary	63.00 FS	*- FS
6	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*- FS
7	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
8	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$)</b>	<b>4,213.00</b>	<b>0.00</b>
-------------------------	-----------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	700.00
3	TO RESPRAY REAR BUMPER	New	900.00	700.00
4	TO CARRY OUT DIAGNISTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,422.00</b>
				<b>1,872.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >