

Vehicle Damage Assessment Report for [SLS6939K]

Estimate Created: 13/08/2022 18:42 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 19/04/2023 01:15 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Audi	Model	A3
Engine Type			
License Plate Number	SLS6939K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	613,390.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$1,872.00 WITH 3 WORKING
DAYS

Insurlogic 5 (19/04/2023 01:14)

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER	REPAIR /	1.0	0.00	0.00 %	0.00
REAR BUMPER SPOILER	X /	1.0	0.00	0.00 %	0.00
REAR BUMPER GUIDE SECTION -LH/RH	X /	1.0	0.00	0.00 %	0.00
REAR BUMPER REINFORCEMENT BEAM	X /	1.0	0.00	0.00 %	0.00
REAR BUMPER BRACKET -LH/RH	X /	1.0	0.00	0.00 %	0.00
REAR PARKING AID SENSOR -INNER /OUTER	X /	1.0	0.00	0.00 %	0.00
REAR PARKING AID SEAL RING	X /	1.0	0.00	0.00 %	0.00
SUNDRIES	X /	1.0	0.00	0.00 %	0.00

Materials Subtotal 0.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO REMOVE AND TRANSFER REAR PARKING AID	RnR	280.00	0.00 %	280.00
TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	RnR	700.00	0.00 %	700.00
TO RESPRAY REAR BUMPER	RnR	700.00	0.00 %	700.00
TO CARRY OUT DIAGNOSTIC CHECK	RnR	192.00	0.00 %	192.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,872.00

Paint Labor Subtotal 0.00

Labor Subtotal 1,872.00

Summary

Repair Cost 1,872.00

Discount(0 %) (0.00)

1,872.00

Excess (0.00)

GST(0.00 %)	0.00
Grand Subtotal	1,872.00