

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0678/2022/EQ
DATE : 11-Aug-22
WIP : 36336

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/08/2022

YOUR INSURED VEH NO : FBT 9005 Z

India International Insurance Pte Ltd

60 Cecil Street

#04-#05 IOB Building

Singapore 049711

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LEE CHONG HUA
ADDRESS : 5 PINE CLOSE
#16-141
SINGAPORE 391005
TELEPHONE : HP +65 96249011
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700058421-04
VEHICLE NO : **SLS 6939 K**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 30/9/2017
ENGINE NO : CHZ 528874
CHASSIS NO : WAUZZZ8V5J1013403
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Aug-22
PLACE OF ACCIDENT : ALONG JALAN BUKIT MERAH FILTERING ROAD TO
CTE TOWARDS OPPOSITE BLK 132 TIONG BAHRU

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6939 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 700	
3	TO RESPRAY REAR BUMPER.	\$ 900.00 700	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,422.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6939 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Repair</i>	1	\$	2,317.00	X
2	REAR BUMPER SPOILER <i>ok</i>	1	\$	264.00	X
3	REAR BUMPER GUIDE SECTION - LH / RH <i>2</i>	2	\$	36.00	X
4	REAR BUMPER REINFORCEMENT BEAM <i>HP</i>	1	\$	642.00	X
5	REAR BUMPER BRACKET - LH / RH <i>HP</i>	2	\$	63.00	X
6	REAR PARKING AID SENSOR - INNER / OUTER <i>ok</i>	2	\$	531.00	X
7	REAR PARKING AID SEAL RING <i>ok</i>	4	\$	10.00	X
8	SUNDRIES		\$	350.00	?
TOTAL SPARE PARTS		:	\$	4,213.00	
TOTAL LABOUR CHARGES		:	\$	2,422.00	
GRAND TOTAL		:	\$	6,635.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *12/08/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorised, 03 Days. Please inform LKIC ~~for~~ to conduct after repairs survey.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: