

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

24/9/2022

M/S AIG INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR NISSAN NV350 - GBL7072J

DOA : 31/07/2022

*Not Allowed
12/10/22
1/s \$1800
4 days*

S/N	QTY	DESCRIPTION			
1	1 PC	REAR BUMPER	Cut	\$	720.60 ✓
2	10 PCS 1 set	REAR BUMPER CLIPS	rec	\$ 30	88.00 ✓
3	1 PC	REAR LH TAIL LAMP	one	\$	242.80 ✓
4	1 PC	REAR LH FENDER	~	\$	2162.20 X
5	1 PC	REAR LH RIM CAP	Cut	\$	174.40 ✓
6	1 PC	REAR LH SLIDING DOOR	~	\$	1430.70 X
				\$	4818.70
			Disc -10%	\$	-481.87
				\$	4336.83
7		REAR LH FENDER STICKER	11	\$	TBC X
8		LABOUR CHARGE		\$	980.00 600
9		SPRAY PAINTING		\$	880.00 600
10		TUFF COAT		\$	11 80.00 X
11		WIRING		\$	30.00 20
12		REVERSE LABOUR CHARGE	for R&R rear reverse sensor	\$	80.00 40
13	Conduct	WHEEL ALIGNMENT		\$	11 80.00 X
			Total	\$	6466.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*1167.8
107
1051.02
1260
2211.02
222
1848*