

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0689/2022/EQ
DATE : 12-Aug-22
WIP : 37077

Xiao Tony

\$1242

032yr

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/08/2022

YOUR INSURED VEH NO : SGQ 198 R

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TAN HWEE SIAN
ADDRESS : 126 SHELFORD ROAD
SINGAPORE 288499

TELEPHONE : HP +65 96660113
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700004012-05
VEHICLE NO : **EU 8838 C**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 29/5/2017
ENGINE NO : CHZ 362117
CHASSIS NO : WAUZZZ8V1H1071888
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Aug-22
PLACE OF ACCIDENT : KONG MEN SAN MONASTERY (OPEN CARPARK)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EU 8838 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	500
4	TO RESPRAY FRONT BUMPER	\$	900.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,852.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EU 8838 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Regis</i>	1	\$ 2,432.00	+	
2	FRONT BUMER GUIDE SECTION - LH <i>3 Not m</i>	1	\$ 43.00	+	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>2</i>	1	\$ 571.00	+	
5	FRONT BUMPER CLOSING ELEMENT - LH <i>Not m</i>	1	\$ 318.00	+	
6	FRONT BUMPER STRIP MOLDING TRIM - LH <i>Not m</i>	1	\$ 182.00	+	
7	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH	1	\$ 42.00	+	
8	RADIATOR GRILLE <i>2</i>	1	\$ 1,578.00	+	
9	RADIATOR GRILLE END PLATE	1	\$ 210.00	+	
10	RADIATOR AIR GUIDE GRILLE - LH <i>Not m</i>	1	\$ 210.00	+	
11	AIR CONDITIONER STICKER	1	\$ 9.00	+	
12	CAUTION SIGN STICKER	1	\$ 16.00	X	
13	FRONT BUMPER RENFORCEMENT BEAM	1	\$ 847.00	+	
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>2 Not m</i>	1	\$ 136.00	+	
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	+	
16	FRONT HIGH TONE SIGNAL HORN RETAINER - LH	1	\$ 213.00	+	
17	FRONT WHEEL HOUSING LINER - LH	1	\$ 183.00	+	
18	HEADLIGHT - LH <i>2</i>	1	\$ 5,879.00	+	
19	LIFT CYLINDER <i>Not m</i>	1	\$ 156.00	+	
20	LIFT CYLINDER HOSE <i>Not m</i>	1	\$ 78.00	+	
SUB TOTAL SPARE PARTS		:	\$ 13,493.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EU 8838 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR AIR GUIDE - LH	1	\$ 28.00	+
22	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 14.00	+
23	FRONT NO PLATE	S/N	\$ 60.00	+
24	SUNDRIES		\$ 300.00	+
TOTAL SPARE PARTS		:	\$ 13,895.00	
TOTAL LABOUR CHARGES		:	\$ 2,852.00	
GRAND TOTAL		:	\$ 16,747.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian
15/08/20

Not Authorised, 03 Days



PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT