

ASS. REC. BY:

REF:

A/GI

Kenneth

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

GIA not ready

Veh No:

SMX 3286A Yr Regn: CI, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius c.c 1798

Colour

M. Red A/C: Insured / Std / NI / NA

Sp. Reading

130689 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

STDKB3FU903092514

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

7 mm

R/Bal.

8 mm

L/Bal.

7 mm

L/Bal.

8 mm

D.O.A.

10/8/22

D.O.I.

11/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Excess

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Sum / I.B.I: (\$

Not Authorized  
 Repair By paint LAD2208-003

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMX3266A**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

11 AUG 2022

**SMX3266A**

JTDKB3FU903092514

201603575K

TOYOTA

PRIUS GEN 4

10/08/2022

**GBK4104B/AIG**

07/01/2021

**PART**

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, FLOOR UNDER, NO.1 LH

| LIST |                  |
|------|------------------|
| \$   | Per/Net 485.60 ✓ |
| \$   | 332.70 ✓         |
| \$   | Net 22.00 ✓      |
| \$   | Per/Net 374.50 ✓ |
| \$   | Per 132.60 X     |
| \$   | Per 39.00 X      |
| \$   | Net 651.00 X     |
| \$   | Per 139.80 X     |
| \$   | Per 241.90 X     |
| \$   | Per 229.90 X     |
| \$   | Per 175.10 X     |

**TOTAL \$ 2,824.10**  
**25% \$ 706.03**  
**\$ 2,118.08**

**Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

|    |                   |
|----|-------------------|
| \$ | Per 700.00 X      |
| \$ | Net 95.00 605.00  |
| \$ | Net 180.00 305.00 |
| \$ | Net 85.00 X       |
| \$ | Net 65.00 X       |

**TOTAL \$ 1,125.00**

**TOTAL PARTS \$ 3,243.08**

**LABOUR**

**Trans-cab Auto Services Pte Ltd****LAD2208-003**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMX3266A**

|                                                                                                                           |    |           |      |
|---------------------------------------------------------------------------------------------------------------------------|----|-----------|------|
| To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.                                      | \$ | nn 300.00 | X    |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | h 380.00  | X    |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 2,200.00  | 2001 |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$ | h 380.00  | X    |
| To transfer of Tailgate fittings, attachments and perform water seepage test.                                             | \$ | h 180.00  | X    |
| To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.                   | \$ | h 480.00  | X    |
| To transfer of Fender fittings, attachments and perform water seepage test.                                               | \$ | h 480.00  | X    |
| To check steering geometry and computer wheel alignment                                                                   | \$ | L 220.00  | X    |
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                                               | \$ | h 250.00  | X    |
| Towing Fees                                                                                                               | \$ | h 150.00  | X    |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 2,200.00  | 2201 |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 170.00    | 501  |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | h 170.00  | X    |
| To transfer of luggage floor panel fittings, attachment and perform water seepage test.                                   | \$ | L 380.00  | X    |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMX3266A**

**LAD2208-003**

To transfer of tire, rim and on wheel balancing.

\$ *nn* 220.00 X

To conduct and perform a comprehensive vehicle diagnostic check  
and reset vehicle warning indicators.

\$ *4* 380.00 X

**TOTAL** \$ **8,540.00**

**Over All Total** \$ **11,783.08**

**(PART-BY-PART) Repair Days**

*25* DAYS

*2 days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: