

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3266A*Not Authorized
Picking B4 paint*

LAD2208-003

1643.53

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

11 AUG 2022**SMX3266A**

JTDKB3FU903092514

201603575K

TOYOTA

PRIUS GEN 4

10/08/2022

GBK4104B/AIG

07/01/2021

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, FLOOR UNDER, NO.1 LH

LIST	
\$	<i>Buc/Med</i> 485.60 ✓
\$	<i>R</i> 332.70 ✓
\$	<i>net</i> 22.00 ✓
\$	<i>net/G</i> 374.50 ✓
\$	<i>SL</i> 132.60 X
\$	<i>SL</i> 39.00 X
\$	<i>R</i> 651.00 X
\$	<i>SL</i> 139.80 X
\$	<i>SL</i> 241.90 X
\$	<i>CM</i> <i>SL</i> 229.90 ✓
\$	<i>R</i> 175.10 X

TOTAL \$ 2,824.10**25% \$ 706.03****\$ 2,118.08****Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	<i>SL</i> 700.00 X
\$	<i>Me</i> 95.00 <i>60SL</i>
\$	<i>Me</i> 180.00 <i>30SL</i>
\$	<i>SL</i> 85.00 X
\$	<i>SL</i> 65.00 X

TOTAL \$ 1,125.00**TOTAL PARTS \$ 3,243.08****LABOUR**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

LAD2208-003**SMX3266A**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Towing Fees	\$	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX3266A

LAD2208-003

To transfer of tire, rim and on wheel balancing. \$ *nn* 220.00 X

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators. \$ *3* 380.00 X

TOTAL \$ 8,540.00

Over All Total \$ 11,783.08

(PART-BY-PART) Repair Days *25 DAYS*

2 day

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: