



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303207

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 19/05/2023  
Reference CC6/CTI22007717/Kya3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SKV 89Z  
Insured Veh. SJF 6737T  
Claim No. SNM22D205539/C02  
Policy No. DMPCSNW00094182200  
Accident Date 07/08/2022  
Inspection Date 11/08/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                              |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                              |                 | Ref: CC6/CTI22007717/Kya3q2<br>Date: 19/05/2023<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                              |                 |                                                              |  |
| Insured Veh.                                                                                                                           | SJF 6737T                                                                                    | Veh. Inspected  | SKV 89Z                                                      |  |
| Policy No.                                                                                                                             | DMPCSNW00094182200                                                                           | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM22D205539/C02                                                                             | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                              | Assign Date     | 11/08/2022                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                              |                 |                                                              |  |
| Make & Model                                                                                                                           | TOYOTA ALPHARD (A)                                                                           | c.c             | 2493                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                       | Year of Reg.    | 2016                                                         |  |
| Chassis No.                                                                                                                            | AGH300071266                                                                                 | Colour          | METALLIC PEARL WHITE                                         |  |
| Odometer                                                                                                                               | 91908 KM                                                                                     | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                     | Modification    | STANDARD ALLOY RIM                                           |  |
| General                                                                                                                                | GOOD                                                                                         |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                              |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                         | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 235/50Z R18                                                                                  | OTANI           | 8 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 235/50Z R18                                                                                  | OTANI           | 8 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 235/50Z R18                                                                                  | OTANI           | 8 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 235/50Z R18                                                                                  | OTANI           | 8 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                              |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                                              |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                              |                 |                                                              |  |
| Accident Date                                                                                                                          | 07/08/2022                                                                                   | Inspection Date | 11/08/2022                                                   |  |
| Survey held at                                                                                                                         | TSR AUTOMOTIVE PTE LTD<br>160 SIN MING DRIVE<br>#06-01 SIN MING AUTOCITY<br>SINGAPORE 575722 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                              |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                              |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                              |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                              |                 | 4 Working Days                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 89Z

| Qty                                | Description of Parts                | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                     |                      |                           |                   |
| 1                                  | FRONT BUMPER                        | BUCKLED              | 2,285.00                  | 1,468.00          |
| 1                                  | FRONT BUMPER REINFORCEMENT          | TO REPAIR SEE LABOUR | 685.00                    | -                 |
| 1                                  | FRONT BUMPER SPONGE                 | SERVICEABLE          | 484.50                    | -                 |
| 1                                  | FRONT BUMPER RETAINER LH            | SERVICEABLE          | 180.00                    | -                 |
| 1                                  | FRONT BUMPER BRACKET LH             | SERVICEABLE          | 220.00                    | -                 |
| 1                                  | FRONT BUMPER GRILLE                 | MTG CRACKED          | 1,258.00                  | 1,124.50          |
| 1                                  | FRONT BUMPER LOWER OUTER GARNISH    | SERVICEABLE          | 780.00                    | -                 |
| 1                                  | FRONT BUMPER SPONGE LH              | SHORTED              | 260.00                    | 260.00            |
| 1                                  | FRONT SUPPORT PANEL                 | TO REPAIR SEE LABOUR | 1,980.00                  | -                 |
| 1                                  | HEADLAMP LH                         | CRACKED              | 3,850.00                  | 3,647.50          |
| 2                                  | HEADLAMP LOWER BRACKET LH           | SERVICEABLE          | 220.00                    | -                 |
| 1                                  | FRONT CENTER GRILLE INNER           | SERVICEABLE          | 580.00                    | -                 |
| 1                                  | FRONT CENTER GRILLE OUTER           | SERVICEABLE          | 485.00                    | -                 |
| 2                                  | FRONT CENTER GRILLE CHROME          | SERVICEABLE          | 780.00                    | -                 |
| 1                                  | FOG LAMP OUTER GARNISH LH           | SCRATCHED / DENTED   | 442.00                    | 181.00            |
| 1                                  | FOG LAMP LH                         | MTG CRACKED          | 398.00                    | 340.00            |
| 1                                  | FRONT FENDER LH                     | TO REPAIR SEE LABOUR | 780.00                    | -                 |
|                                    | LESS 25% DISCOUNT                   |                      | -3,916.88                 | -1,755.25         |
|                                    |                                     |                      | 11,750.62                 | 5,265.75          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                     |                      |                           |                   |
| 1                                  | SET 360 DEGREE VIEW CAMERA (SN)     | SHORTED              | 2,000.00                  | 2,000.00          |
| 1                                  | FRONT GRILLE INNER LAMP (SN)        | SERVICEABLE          | 450.00                    | -                 |
| 1                                  | SET FRONT NO PLATE WITH FRAME (SN)  | SERVICEABLE          | 60.00                     | -                 |
| 1                                  | SET FRONT BUMPER LOWER SPOILER (SN) | TO REPAIR SEE LABOUR | 4,000.00                  | -                 |
| 1                                  | HEADLAMP LH OUTER STRIKER           | NECESSARY            | 150.00                    | 80.00             |
|                                    |                                     |                      | 6,660.00                  | 2,080.00          |

Report Ref No. CC6/CTI22007717/Kya3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                | Description of Parts                                                                                                                                                                                                  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                    | <b>LABOUR</b>                                                                                                                                                                                                         |               |                           |                   |
|                                    | LABOUR CHARGE TO REPAIR ,REPLACE ,ALIGN ADJUST ,REMOVE & REFIX ACCIDENT AFFECTED AREA .INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,FRONT SUPPORT PANEL ,FRONT FENDER LH AND SET FRONT BUMPER LOWER SPOILER. |               | 800.00                    | 300.00            |
|                                    | TO DO ANTI RUST.                                                                                                                                                                                                      | NOT NECESSARY | 90.00                     | -                 |
|                                    | TO CHECK WIRING SYSTEM ,FORCUS HEADLAMPS ETC.                                                                                                                                                                         |               | 120.00                    | 20.00             |
|                                    | TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA (PEARL WHITE).                                                                                                                                                         |               | 800.00                    | 450.00            |
|                                    | LABOUR TO INSTALL SENSOR ,360 VIEW CAMERA ,ACCESSORIES WORK .                                                                                                                                                         |               | 300.00                    | 150.00            |
|                                    | TO INSTALL BODY KITS.                                                                                                                                                                                                 |               | 120.00                    | 80.00             |
|                                    | TO DO COMPUTER SETTING,DIGANOSE DELETE FAULT CODE AFTER REPAIR.                                                                                                                                                       | NOT NECESSARY | 250.00                    | -                 |
|                                    |                                                                                                                                                                                                                       |               | 2,480.00                  | 1,000.00          |
|                                    | <b>GRAND TOTAL</b>                                                                                                                                                                                                    |               | <b>20,890.62</b>          | <b>8,345.75</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                                                                                                                                       |               |                           | <b>8,345.75</b>   |

Report Ref No. CC6/CTI22007717/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKV 89Z

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



TOYOTA MOTOR CORPORATION  
MODEL DBA-AH30W-PEASK  
ENGINE 2AS-FE  
FRAME No. AGH30-0071266  
COLOR TRIM PLANT  
070 FC21 C31  
TRANS / AXLE K115 -01A





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 89Z

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKV 89Z

### RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

