

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YP 6692H Yr Regn: 28/6/17
 Type: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW FSR34 c.c. 1790
 Colour: White A/C: Insured / Std / Nil / NA
 Sp. Reading: 118873 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: JALESS 347H 7000017
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 265/70R19.5
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 7/8/22 D.O.I. 15/8/22
 Survey held at Sing Hb. Tee
 Des. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-881</u>
<u>7/2/23</u>	<u>Steve finalised LS \$9000; 12 days with repainer. (Red 4783.40, 342)</u>

Date/Time, File Pass to?

☐ : Prelim. Report☒ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: ODLump Sum / L.B.J. (\$ \$9000)Days Of Repair: 12

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **ERGO Insurance Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	DMCG22003532	Date of Loss:	02/08/2022
Vehicle Reg. No.:	YP6692H	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SL7 EATING HOUSE	Contact No:	+6588582297
Driver:	LIU XINYE		
Make/Model:	ISUZU FSR34P, 7.8 D (M)	Vehicle Reg. Date:	28/06/2017
Vehicle Colour:	White		
Engine No:	6HK1696274	Chassis No:	JALFSR347H7000017
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	8,922.10
Miscellaneous Items	0.00
Labour	3,450.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,372.10
+ GST 7.00% (\$\$)	866.05
Nett Amount (\$\$)	13,238.15

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Aug 2022)

Parts: N/A ISUZU FSR34P 7.8 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/YP6692H/23/08/2022 15:45

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE ✓ BR	0.00	0.00	*25.00 F ✓
2	1		*FRT BUMPER ✓ DD	0.00	0.00	*780.00 F ✓
3	2		*FRT BUMPER LOWER CTR SIDE GARNISH LH/RH ✓ CRU	0.00	0.00	*50.00 F ✓
4	2		*FRT BUMPER UPPER STEP GARNISH ✓ NEC	0.00	0.00	*56.00 F ✓
5	2		*FRT BUMPER BRACKET ? BT	0.00	0.00	*110.00 F ✓
6	1		*FRT GRILLE ✓ BR	0.00	0.00	*485.00 F ✓
7	2		*FRT GRILLE LOWER APRON X NN	0.00	0.00	*20.00 F X
8	10		*FRT GRILLE CLIPS(+) ✓ NEC	0.00	0.00	15 ✓ *50.00 F
9	10		*FRT GRILLE CLIPS(-) ✓ NEC	0.00	0.00	15 ✓ *50.00 F
10	1		*FRT PANEL ✓ DD	0.00	0.00	*1,100.00 F ✓
11	2		*FRT PANEL HINGE ? nn	0.00	0.00	*180.00 F X
12	2		*FRT PANEL LOCK ? nn	0.00	0.00	*100.00 F X
13	1		*FRT PANEL ISUZU LOGO ✓ NEC	0.00	0.00	*120.00 F ✓
14	2		*FRT HEADLAMP ✓ BR	0.00	0.00	*520.00 F ✓
15	2		*FRT SIGNAL LAMP ✓ BR	0.00	0.00	*160.00 F ✓
16	2		*FRT CORNER PANEL ✓ BR	0.00	0.00	*380.00 F ✓
17	2		*FRT CORNER PANEL SEAL ?	0.00	0.00	*40.00 F ✓
18	1		*FRT WIPER PANEL ✓ DD	0.00	0.00	*185.00 F ✓
19	2		*FRT WIPER ARM ✓ BT	0.00	0.00	*210.00 F ✓
20	2		*FRT WIPER BLADE ✓ CRU	0.00	0.00	*70.00 F ✓
21	2		*FRT STEP GARNISH ✓ BR	0.00	0.00	*290.00 F ✓
22	1		*FRT WINDSCREEN ✓ NEC	0.00	0.00	*1,500.00 F ✓
23	1		*FRT WINDSCREEN TOP MOULDING ✓ NEC	0.00	0.00	*100.00 F ✓
24	1		*FRT WINDSCREEN SEALANT ✓ NEC	0	0.00	*40.00 FS ✓ nett
25	1		*ERP BRACKET ✓ NEC	0	0.00	*26.00 FS ✓ nett
26	1		*FRT WINDSCREEN LOWER MOULDING ✓ NEC	0.00	0.00	*120.00 F ✓
27	1		*FRT CHASSIS CROSSMEMBER ? X nn	0.00	0.00	*650.00 F X
28	2		*FRT CHASSIS CROSSMEMBER BRACKET ? X nn	0.00	0.00	*700.00 F X

F=Franchise part. S=SpcNett.

6331
+10%
6964.10

nett - 66

Sub Total (S\$) 8,117.00
+ Margin on L,N Items 10.00% (S\$) 805.10

Total Parts (S\$) 8,922.10

Sng Ah Tee Motor & Panel Service Pte Ltd/YP6692H/23/08/2022 15:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New 1400	1,600.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New 1000	1,200.00
3	TO CHECK WIRING	New 30	50.00
4	TO DIAGNOSE & RESET FAULT CODE	New 50	100.00
5	TO REMOVE & REFIX FRT WINDSCREEN	New	150.00 ✓
6	TO REMOVE & REFIX FRT DASHBOARD	New 200	250.00
7	TOP UP AIRCON GAS	New	100.00 ✓
2930			
Gross Labour Cost (S\$)			3,450.00

Sng Ah Tee Motor & Panel Service Pte Ltd/YP6692H/23/08/2022 15:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

supp - 1268.30

= 11,228.40

Steve (LKK)
15/08/22, 3.00pm
OD - Not Authorise
Excess - ?
Resurvey Before Spray
12 days

L/S - 8982.72
= 9000

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Jan 2023)

Parts: N/A ISUZU FSR34P 7.8 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/YP6692H/06/01/2023 17:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIRCON BLOWER ASSY ✓ BR	0.00	0.00	*850.00 F ✓
2	8		*FRT PANEL SIDE CLIP ✓ NEC	0.00	0.00	*24.00 F ✓
3	8		*FRT CORNER PANEL CLIP (SQUARE) ✓ NEC	0.00	0.00	*24.00 F ✓
4	1		*FRT PANEL TOP SEAL ✓ TN	0.00	0.00	*75.00 F ✓
5	2		*FRT BUMPER BRACKET ✓ BT X nn	0.00	0.00	*130.00 F X
6	1		*BRAKE MASTER PUMP BASE HOLDER ✓ BR	0.00	0.00	*180.00 F ✓

F=Franchise part.

Sub Total (\$\$)	1153	1,283.00
+ Margin on L,N Items 10.00% (\$\$)	+10%	128.30
Total Parts (\$\$)	1268.30	1,411.30

Sng Ah Tee Motor & Panel Service Pte Ltd/YP6692H/06/01/2023 17:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS