

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	INCOME INSURANCE LTD		Ref	f:	CS3/INC22007731/Sny3m4	
	75 BRAS BASAH R INCOME CENTRES	Dat	te:	11/11/2022		
	ATTN: JEFF LIN		Cod	de:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SNF 9842E	Veh. Inspected		SNE 1361J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1184014-001	Excess (\$)		0.00	
	Assign From	DIANA TAY	Assign Date		15/08/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2022	
	Chassis No.	RV31000694	Colour		RED	
	Odometer	023603 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55ZR17	LAUFENN		8 mm	
	L/H Front Tyre	215/55ZR17	LAUFENN		8 mm	
	R/H Rear Tyre	215/55ZR17	LAUFENN		7 mm	
	L/H Rear Tyre	215/55ZR17	LAUFENN		7 mm	
4.	Description of Damages					
	THE VEHICLE SUS	ICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
5. General Information						
	Accident Date	06/08/2022	Inspect Date / Time	е	15/08/2022 (03:14 PM)	
	Survey held at	D'S GRAFFITI CONCEPTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-26 SYNERGY @ KB SINGAPORE 417800				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/INC22007731/Sny3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser