

ASS. REC BY: T. J. J. J.REF: CO/ INC 22007739/Tvg 3

ASSIGNMENT

GE 2026 April

2006, April

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspec/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$11K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBA 4339T Yr Regn: 2006, April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB400 C.C. 399Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SH2NC 39915M100258

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R17

R: _____

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 15/8/22Survey held at: Engat Lee MotorDes. of Damages: Frt / Rear O/S / NI / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

S + RS. \$ _____

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. / % _____

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 10-Aug-22

Estimate no.

1142

Plate No. FBA 4339 T

Model. HONDA CB 400

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 800.00	} <i>SN120</i>	
2	FORK T - UNDER BRACKET	\$ 500.00		
3	STEERING CONE	\$ 250.00	X	
4	FRONT SPORT RIM	\$ 500.00	X	
5	FRONT DISC BRAKE	\$ 400.00	X	
6	FRONT TYRES	\$ 300.00	X	
7	HANDLE BAR	\$ 280.00	?	
8	HANDLE BAR BRACKET	\$ 250.00	?	
9	HANDLE BAR END	\$ 100.00	<i>cut</i>	
10	MIRROR SET	\$ 120.00	<i>cut</i>	
11	BRAKE LEVER	\$ 120.00	<i>bt</i>	
12	TROTTLER CABLE	\$ 200.00	<i>bt</i>	
13	HEAD LIGHT	\$ 350.00	?	
14	HEAD COVER	\$ 280.00	<i>cut</i>	
15	FRONT SIGNAL LIGHT	\$ 150.00	X	
16	CRASH BAR	\$ 280.00	<i>bt</i>	
17	EXHAUST PIPE	\$ 800.00	<i>del</i>	
18	EXHAUST BRACKET	\$ 200.00	<i>cut</i>	
19	REAR SIGNAL LIGHT	\$ 120.00	<i>bt</i>	
20	LABOUR	\$ 500.00	250	

Tan Kim 97495749 / 62563561

WP 15/8/22 e Ypr

1/3 Resurvey after repair

3 days

To check consistency of accident

To check part prices

To forward accident report

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 650.00

Sub Total : \$ 5,850.00

GST 7% \$ 409.50

Total: \$ 6,259.50

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.