

ASS. REC. BY:

REF:

EQ/ 22007744/KC

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLN 5343L

Yr Regn:

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Esquire

c.c.

1797

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

7386

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZWR 80 - 0232912

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

10/8/22

D.O.I.

16/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

) \$ + RS. \$

) Fines

) Others

Report Format :

mp Sum / I.B.I: (\$

TOTAL

# AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A  
#01-09 AMK AUTOPOINT Singapore 568047  
Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST Reg No: M9-0009639-E

TP INSURER:

EQ Insurance Company Ltd (HQ)

Singapore

**SURVEYOR COPY**

## PARTICULARS OF CLAIM

Claim Type: THIRD PARTY  
Policy No: *L1111*  
Vehicle Reg. No.: **SLN5343L**  
Party At Fault: UNKNOWN  
Driver (TP): GOH WEE CHENG EVELYN  
Ref. No:  
Date of Loss: 10/08/2022  
Driveable?

Make/Model: TOYOTA ESQUIRE, 1.8 HYBRID 7-SEATER GI CVT (A)  
Vehicle Colour: WHITE  
Engine No: 2ZR1902659  
Odometer: 0 KM  
Vehicle Reg. Date: 08/05/2017  
Chassis No: ZWR800232912

Paint Type:  
Total Loss?  
Est. Duration of Repair (day)

NO

*7*

*Not Withheld  
Repairing By repair  
6 days*

Remarks: CAR IN @ ALM AMK AUTOPOINT WORKSHOP

Present Location: AH LIM MOTOR COMPANY (AMK)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

## COST OF CLAIMS

	Amount
Parts	2,941.60
Miscellaneous Items	0.00
Labour	2,520.00
Paintwork Labour	0.00
Polishing	0.00
<b>Gross Total (\$\$)</b>	<b>5,461.60</b>
<b>+ GST 7.00% (\$\$)</b>	<b>382.31</b>
<b>Nett Amount (\$\$)</b>	<b>5,843.91</b>

is claim is handled by: ZILA



Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 12 Aug 2022)
Parts:	M1-MPV TOYOTA ESQUIRE 1.8 HYBRID 7-SEATER GI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Ah Lim Motor Company/SLN5343L/12/08/2022 17:44
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*REAR WINDSCREEN MLDG LH & RH	Nu 0.00	0.00	*60.00 F
2	1		*TAILGATE	Bj 0.00	0.00	*550.00 F
3	1		*TAILGATE ESQUIRE LOGO	Nu 0.00	0.00	*25.00 F
4	1		*TAILGATE HYBRID SYNERGY DRIVE LOGO	Nu 0.00	0.00	*25.00 F
5	1		*TAILGATE LOCK		0.00	*180.00 F
6	1		*TAILGATE LOCK CATCH		0.00	*20.00 F
7	1		*TAILGATE PULL HANDLE		0.00	*250.00 F
8	1		*TAILGATE INNER TRIM BTM		0.00	*140.00 F
9	1		*TAILGATE RUBBER	Nu/DH 0.00	0.00	*295.00 F
10	1		*REAR BUMPER	Bj 0.00	0.00	*12.00 F
11	1		*REAR BUMPER TOW COVER LH	CM 0.00	0.00	*25.00 F
12	1		*REAR BUMPER REFLECTOR LH	Sm 0.00	0.00	*60.00 F
13	1		*REAR BUMPER SIDE RETAINER LH	DI 0.00	0.00	*9.00 F
14	6		*REAR BUMPER CLIPS	Nu 0.00	0.00	*40.00 F
15	1		*REAR ELECTRICAL KEY ANTENNA		0.00	*260.00 F
16	1		*REAR END PANEL	Bj 0.00	0.00	*85.00 F
17	1		*REAR END PANEL GARNISH	Nu 0.00	0.00	*350.00 F
18	1		*REAR FLOOR TOP COVER		0.00	*- F
19	1		*REAR FLOOR MAT - CHECK PRICE		0.00	*- F
20	1		*LUGGAGE COMPARTMENT TRIM BOX - CHECK PRICE		0.00	*20.00 FS
21	1		*INNER SEAL	Nu 0	0.00	*40.00 FS
22	1		*WINDSCREEN SEALANT	Nu 0	0.00	*35.00 FS
23	1		*NUMBER PLATE	Sm 0	0.00	*200.00 FS
24	1		*REVERSE SENSOR	Nu 0	0.00	

F=Franchise part. S=SpcNett.

Sub Total (\$)	2,701.00
+ Margin on L,N Items 10.00% (\$)	240.60
Total Parts (\$)	2,941.60

Ah Lim Motor Company/SLN5343L/12/08/2022 17:44. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00

Ah Lim Motor Company/SLN5343L/12/08/2022 17:44. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

ulars

		Lab.Type	Amount	
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.			
3	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	120.00	✓
		New	180.00	801
4	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	60.00	✓
5	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	60.00	501
6	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00	✓
7	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	1,000.00	701
8	TO SPRAY TAILGATE;REAR BUMPER;RR END PANEL; SPARE TYRE PANEL.	New	1,000.00	6601
Gross Labour Cost (\$\$)			2,520.00	

Ah Lim Motor Company/SLN5343L/12/08/2022 17:44. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	11/08/2022 17:09 (SGT)
Reported by	Driver
Date of Accident	10/08/2022 17:30 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE TURNING INTO AMK AVE 3
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN5343L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHEONG JEE MENG EDDY
NRIC No	SXXXX767J
Email Address	evegwc@gmail.com
Mobile Phone No	(Phone) +65-97613822
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Esquire
Variant	ESQUIRE HYBRID 1.8 GI CVT 2WD
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1797

### INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MT/01037150


### DRIVER

Name of Driver	GOH WEE CHENG EVELYN
NRIC No	SXXXX058A
Date Of Birth	27/09/1973
Occupation	Indoor





Date of accident: 10/8/22 Time: 5:30 pm Location: CTE turning into Ank Ave 3  
My Vehicle A: SLN 5343 L Vehicle B: GBB 7950 C Vehicle C: \_\_\_\_\_  
SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped at traffic light, 2nd car on the left most lane to waiting for traffic light to be in my favour to turn into Ang Mo Kio Ave 3. A van rammed into my car from behind and I had to jam brake to prevent my car from rolling forward and hit the car in front. The driver of GBB 7950 C was cooperative in giving me his contact number and a copy of his driver's license.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Zila  
Ah Lim Motor Company