

Vehicle Diagnostic Report

The Report is created by **LAUNCH X431**

Repair Shop

Shop Name: AH LIM MOTOR COMPANY
 Address: No 10 Ang Mo Kio Ind Park 2A #01-09 Singapore Singapore
 Zip Code: 568047
 Telephone: 64831244
 Email: ahlmmc@singnet.com.sg
 SN: 989820004237
 Test Time: 2022-08-24 08:54:40



Vehicle Information

License #: SLN5343L
 Year: 2014
 Make: Toyota
 Model: Noah HV/Voxy HV/Esquire HV
 Odometer: 73667 miles
 Vehicle Software Version: V50.40
 Diagnostic Application Version: V7.03.013
 Diagnostic path: 16PIN DLC(Japan) > Noah HV/Voxy HV/Esquire HV > 2ZR-FXE > 2019.01-2021.12



System fault code

The following system is abnormal:

Air Conditioner 2 problems exist

- | | |
|--|---------|
| 1.B1419 Rear Room Temperature Sensor Circuit | Current |
| 2.B1419 Rear Room Temperature Sensor Circuit | History |

Main Body 2 problems exist

- | | |
|---|---------|
| 1.B2321 Driver Door Motor ECU Communication Stop | History |
| 2.B1206 Power Window Master SW ECU Communication Stop | History |

Rear Right Door 1 problem exist

- | | |
|---|---------|
| 1.B2254 Door Closer Switch Failure on Rear Right Door | History |
|---|---------|

The following systems are OK:

- 1.Engine
- 2.Hybrid Control
- 3.Cruise Control
- 4.Transmission Control
- 5.ABS/VSC/TRC(TRAC)
- 6.EMPS
- 7.SRS Airbag

8. Combination Meter
9. HL AutoLeveling
10. Rear Left Door
11. D-Door Motor
12. P-Door Motor
13. RL-Door Motor
14. RR-Door Motor
15. Central Gateway
16. Master Switch
17. Entry&Start
18. Power Source Control
19. PCS/LDA/RSA/LVN