



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22007748/Ucy3q2	
			Date: 22/09/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJG 2151D	Veh. Inspected	GBF 6682L	
Policy No.	D22MTPV01006277	Coverage (\$)	0.00	
Claim No.	CMTD2202748/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	15/08/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA LITEACE 1.5 GL (A)	c.c	1495	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	S402M0061337	Colour	SILVER	
Odometer	54219 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	165 R13	ARIVO	6 mm	
L/H Front Tyre	165 R13	ARIVO	6 mm	
R/H Rear Tyre	165 R13	ARIVO	6 mm	
L/H Rear Tyre	165 R13	ARIVO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/08/2022	Inspection Date	15/08/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	