

YSK AUTO WORKSHOP

1 KAKI BUKIT AVENUE 6, BLK D # 01-71

REGISTRATION NO. / UNIQUE ENTITY NUMBER : 53311047E

TP INC

VERON.

DATE : 13/08/2022

VEHICLE NO : SMQ9559C HYUNDAI AVANTE

CHASSIS: KMHD841CMLU028996

ITEMS	QTY	Amount
1 BONNET <i>Painted</i>	1	<u>\$1,910.30</u>
2 BONNET LOCK <i>new</i>	1	\$129.90
3 BONNET HINGE LH <i>new</i>	1	\$49.10
4 FRONT BUMPER <i>Delivered</i>	1	\$474.40
5 FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$24.10
6 FRONT BUMPER SPONGE <i>cut</i>	1	\$110.70
7 FRONT BUMPER FOG LAMP LH <i>cut</i>	1	\$164.80
8 FRONT BUMPER SIDE AIR VENT LH <i>cut</i>	1	\$33.60
9 FRONT BUMPER LOWER SIDE GARNISH LH <i>cut</i>	1	\$115.40
10 FRONT BUMPER LOWER SPOILER <i>Delivered</i>	1	\$121.70
11 FRONT BUMPER CENTER TOP RUBBER <i>new</i>	1	\$42.60
12 FRONT GRILLE <i>cracked</i>	1	<u>\$1,214.30</u>
13 FRONT HEADLAMP LH <i>cracked</i>	1	\$1,756.40
14 FRONT HEADLAMP LOWER BRACKET LH <i>cracked</i>	1	\$24.60
15 FRONT HEADLAMP TOP GARNISH LH <i>Delivered</i>	1	\$84.50
16 FRONT SUPPORT PANEL <i>new</i>	1	\$949.30
17 FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$84.50
18 FRONT FENDER LH <i>Brickland</i>	1	\$1,227.70
19 FRONT FENDER INNER COWLING LH <i>new</i>	1	\$85.70
20 FRONT RESONATOR TANK LH <i>new</i>	1	\$87.50
21 FRONT RESONATOR TANK AIR DUCT LH <i>new</i>	1	\$94.10
22 FRONT DOOR LH <i>Repair</i>	1	\$1,904.70
23 FRONT DOOR OUTER HANDLER WITH SENSOR <i>cut</i>	1	\$179.10
24 REAR DOOR LH <i>Repair</i>	1	\$1,775.20

DISCOUNT 20%

TOTAL

\$12,644.20

\$2,528.84

\$10,115.36

SPECIAL NETT ITEM		QTY	Amount
1	FRONT BUMPER CLIPS <i>new</i>	1	\$80.00 <i>30</i>
2	FRONT FENDER INNER COWLING CLIPS LH <i>new</i>	1	\$60.00 <i>+ 30</i>
3	FRONT DOOR INNER TRIM BOAR DCLIPS LH <i>new</i>	1	\$50.00 <i>+</i>
4	REAR DOOR INNER TRIM BOARD CLIPS LH <i>new</i>	1	\$50.00 <i>+</i>
			\$240.00
			\$10,355.36

Labour charges

1	TO REMOVE , REINSTALL ALL ELECTRICAL WIRING , LIGHTING	\$80.00 <i>30</i>
2	TO SUPPLY LABOUR ,WORKMANSHIP TO REMOVE /REINSTALL AND PANEL BEAT AFFECTED ACCIDENT AREAS	<i>1810</i> \$1,600.00 <i>700</i>
3	TO SPRAY PAINT AND RESPRAY ACCIDENT AFFECTED AREAS	\$1,500.00 <i>1000</i>
4	TO SUPPLY LABOUR REMOVE & REINSTALL BOTH LH DOORS FITTING	\$400.00 <i>+</i>
5	TO APPLY TUFF COAT	\$300.00 <i>80</i>
		\$3,880.00
		\$14,235.36

14,420.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
h/s 15/08/22
06 Days

Supplementary: 185-60

Total: 8008.88

h/s: 6.4K

6.4K

YSK AUTO WORKSHOP

1 KAKI BUKIT AVENUE 6, BLK D # 01-71

REGISTRATION NO. / UNIQUE ENTITY NUMBER : 53311047E

DATE : 13/08/2022

VEHICLE NO : SMQ9559C HYUNDAI AVANTE

CHASSIS: KMHD841CMLU028996

SUPPLEMENTARY / ADDITION

ITEMS

- 1 FRONT BUMPER LOWER BEAM
- 2 FRONT BUMPER UNDER COVER

*cracked.
Repaired*

QTY	Amount
1	✓ \$98.70
1	✓ \$133.30

\$232.00

DISCOUNT 20%

\$46.40

TOTAL

\$185.60

*Supplementary : 232
185.60*