



Your Ref : 202222006096SL

Date: 26<sup>th</sup> Aug 2022

Our Ref : CS4/AIS22007758/Nvy3m4

**M/s Allianz Insurance Singapore Pte Ltd**

79 Robinson Road #09-01

Singapore 068897

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKT 6298H  
ACCIDENT ON 11/08/2022**

Instruction was received to inspect the vehicle Reg. No. SKT 6298H. The inspection was conducted on 16/08/2022 at the premises of M/s Auto Insure Pte Ltd, 6 Marsiling Lane, Singapore 739145.

The following vehicle information was recorded:

Registration Number : SKT 6298H  
Make/Model : Honda Vezel 15X CVT  
Year of Registration : 2015  
Body Colour : Silver  
Chassis Number : RU11021543  
Engine Capacity : 1496 cc  
Speedometer Reading : N.A (battery melted)

The vehicle caught fire. The cause of fire probably due to electrical short circuit from original components. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 46,000.00 (est)
Less: LTA Reimbursement Value (RV)	S\$ 23,579.00
Nett Liability	<u>S\$ 22,421.00</u> =====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)  
Technical Investigator  
LL.B. (Hons) London



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.