



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION		
INCIDENT NO.: /20220811/0522	LOCATION OF FIRE:	
FIRE REPORTED ON: 11 August 2022	Along PIE towards Changi Airport	
TIME OF CALL: 11:36:29 hrs	before Bedok Reservoir Road exit	
STATION	Near lamp post no. 370 (Singapore)	
COVERAGE: Changi Fire Station		
2. INCIDENT INFORMATION		
FIRE INVOLVED: Fire involved a Honda car (SKT 6298H).		
METHOD OF EXTINGUISHMENT: By SCDF crew using a 38mm hose line jet from fire appliance.		
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the dashboard / components/ wirings and connections)		
DAMAGE OBSERVED*: As a result of the fire, the Honda car (SKT 6298H) was completely damaged. The road side metal barrier, road tarmac and nearby tree in the immediate surrounding sustained varying degrees of heat and smoke damage.		
3. FATALITY/INJURY INFORMATION		
NAME	NRIC/FIN	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL
REPORT ISSUED BY: ANG LI FENG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE		

**This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

This is a computer generated report. No signature is required.