

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2200259
Date: 12 Aug 2022

Veh Reg No: SLC5736U
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT
Chasis No: JM6BM42A8G0338826
Reg. Date: 19/05/2016
Your Ref No: YM9043C

Claim Type: Third Party
Accident Date: 11/08/2022
TP Veh Reg No: YM9043C

Estimate Repair Cost to Vehicle No :SLC5736U

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC REAR DOOR RH	1,049.40	
2	2 PCS REAR DOOR HINGE RH	156.60	
3	1 PC REAR DOOR RH CHECKER	61.40	
4	1 PC REAR DOOR OUTER HANDLE RH	168.10	
5	1 PC REAR DOOR OUTER HANDLE COVER RH	52.70	
6	1 PC REAR DOOR CHROME MOULDING RH	197.30	
7	1 PC REAR DOOR SHORT CHROME MOULDING RH	71.60	
8	1 PC REAR DOOR GLASS RH	399.70	
9	1 PC REAR DOOR GLASS CHANNEL RUBBER	142.70	
10	1 PC REAR DOOR GLASS CHANNEL PILLAR RH	69.20	
11	1 PC REAR DOOR REGULATOR ASSY RH	338.90	
12	1 PC REAR DOOR FRAME BLACK TAPE RH	51.60	
13	1 PC REAR DOOR LOCK RH	288.70	
14	1 PC REAR DOOR LOCK CHECKER RH	41.30	
15	1 PC REAR DOOR RUBBER RH	196.80	
16	1 PC REAR DOOR TRIM RH	434.30	
17	1 PC REAR DOOR ANGLE GLASS RH	197.70	
18	1 PC REAR FENDER RH	1,233.80	
19	1 PC REAR WINDSCREEN RUBBER	126.90	
20	1 PC TAIL LAMP - RH	534.90	
21	1 PC REAR BUMPER	1,168.20	
22	1 PC REAR BUMPER RETAINER RH	48.00	
23	1 PC REAR FENDER COWLING RH	183.20	
24	1 PC REAR SPORTS RIM RH	1,156.80	
25	1 PC REAR LOWER ARM RH	362.80	
26	1 PC REAR KNUCKLE ARM RH	686.40	
27	1 PC REAR RH FENDER WHEEL HUB WITH BEARING	434.90	
28	1 PC REAR SHOCK ABSORBER RH	362.40	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2200259
Date: 12 Aug 2022

Veh Reg No: SLC5736U
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT

Chasis No: JM6BM42A8G0338826

Claim Type: Third Party

Accident Date: 11/08/2022

TP Veh Reg No: YM9043C

Reg. Date: 19/05/2016

Your Ref No: YM9043C

Estimate Repair Cost to Vehicle No :SLC5736U

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29	1 PC REAR RH TRAILING ARM	412.00	
30	1 PC REAR TOP ARM RH	190.90	
31	1 PC REAR STAY ARM RH	181.00	
32	1 PC REAR CROSSMEMBER RH	867.60	
		11,867.80	
	Less 20%	2,373.56	9,494.24
	Special Net		
33	1 SET REAR DOOR TRIM CLIPS RH	60.00	
34	1 PC REAR WINDSCREEN INNER SEAL RUBBER	60.00	
35	1 PC REAR WINDSCREEN SEALANT	60.00	
36	1 SET REAR RH FENDER COWLING CLIPS	60.00	
37	1 SET REAR BUMPER CLIPS	40.00	
38	1 PC REAR TYRE RH	380.00	
		660.00	660.00
	Labour		
39	1 TO CHECK WIRING	50.00	
40	1 (REAR) TO REMOVE AND REFIT WINDSCREEN GLASS	120.00	
41	1 TO REMOVE AND REFIT SEAT CUSHION & INNER TRIM	200.00	
42	1 TO REMOVE AND REFIX REAR DOOR GLASS RH	100.00	
43	1 TO REMOVE AND REFIT ANGLE GLASS	80.00	
44	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
45	1 TO REMOVE AND REFIT UNDERCARRIAGE	580.00	
46	1 (REAR) TO CHECK WHEEL ALIGNMENT	120.00	
47	1 TO SPRAY PANEL SEALANT	150.00	
48	1 (REAR) TO SPRAY PAINTING	1,400.00	
49	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,000.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/08/2022
TP Veh Reg No: YM9043C

Estimate No: EST2200259
Date: 12 Aug 2022

Veh Reg No: SLC5736U
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT
Chasis No: JM6BM42A8G0338826
Reg. Date: 19/05/2016
Your Ref No: YM9043C

Estimate Repair Cost to Vehicle No :SLC5736U

Quantity	Description	List Price	Amount
		S\$	S\$
		4,880.00	4,880.00
Total			S\$ 15,034.24
Add GST @ 7%			1,052.40
Total Amount Payable			S\$ 16,086.64

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND EIGHTY SIX AND CENTS SIXTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE