

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2200259

Date: 12 Aug 2022

Veh Reg No: SLC5736U

Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT

Chasis No: JM6BM42A8G0338826

Reg. Date: 19/05/2016

Your Ref No: YM9043C

Claim Type: Third Party

Accident Date: 11/08/2022

TP Veh Reg No: YM9043C

Estimate Repair Cost to Vehicle No :SLC5736U

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR DOOR RH <i>Distorted</i>	1,049.40	✓
2	2 PCS REAR DOOR HINGE RH <i>Best</i>	156.60	✓
3	1 PC REAR DOOR RH CHECKER <i>Dist</i>	61.40	✓
4	1 PC REAR DOOR OUTER HANDLE RH <i>Dist</i>	168.10	✓
5	1 PC REAR DOOR OUTER HANDLE COVER RH <i>Dist</i>	52.70	✓
6	1 PC REAR DOOR CHROME MOULDING RH <i>Dist</i>	197.30	✓
7	1 PC REAR DOOR SHORT CHROME MOULDING RH <i>Dist</i>	71.60	✓
8	1 PC REAR DOOR GLASS RH <i>Shattered</i>	399.70	✓
9	1 PC REAR DOOR GLASS CHANNEL RUBBER <i>new</i>	142.70	✓
10	1 PC REAR DOOR GLASS CHANNEL PILLAR RH <i>Best</i>	69.20	✓
11	1 PC REAR DOOR REGULATOR ASSY RH <i>Dist</i>	338.90	✓
12	1 PC REAR DOOR FRAME BLACK TAPE RH <i>new</i>	51.60	✓
13	1 PC REAR DOOR LOCK RH <i>Dist</i>	288.70	✓
14	1 PC REAR DOOR LOCK CHECKER RH <i>new</i>	41.30	✓
15	1 PC REAR DOOR RUBBER RH <i>Dist</i>	196.80	✓
16	1 PC REAR DOOR TRIM RH <i>Dist</i>	434.30	✓
17	1 PC REAR DOOR ANGLE GLASS RH <i>new</i>	197.70	✓
18	1 PC REAR FENDER RH <i>Distorted</i>	1,233.80	✓
19	1 PC REAR WINDSCREEN RUBBER <i>new</i>	126.90	✓
20	1 PC TAIL LAMP - RH <i>new</i>	534.90	✓
21	1 PC REAR BUMPER <i>Dist</i>	1,168.20	✓
22	1 PC REAR BUMPER RETAINER RH <i>Dist</i>	48.00	✓
23	1 PC REAR FENDER COWLING RH <i>at</i>	183.20	✓
24	1 PC REAR SPORTS RIM RH <i>at</i>	1,156.80	✓
25	1 PC REAR LOWER ARM RH <i>Best</i>	362.80	✓
26	1 PC REAR KNUCKLE ARM RH <i>Dist</i>	686.40	✓
27	1 PC REAR RH FENDER WHEEL HUB WITH BEARING <i>Dist</i>	434.90	✓
28	1 PC REAR SHOCK ABSORBER RH <i>Best</i>	362.40	✓

original 1,156.80 600(sw)

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2200259

Date: 12 Aug 2022

Veh Reg No: SLC5736U
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chasis No: JM6BM42A8G0338826
Reg. Date: 19/05/2016
Your Ref No: YM9043C

Claim Type: Third Party
Accident Date: 11/08/2022
TP Veh Reg No: YM9043C

Estimate Repair Cost to Vehicle No :SLC5736U

Quantity	Description	List Price	Amount
		SS	SS
29	1 PC REAR RH TRAILING ARM <i>Best</i>	412.00 <i>2</i>	
30	1 PC REAR TOP ARM RH <i>Best</i>	190.90 <i>2</i>	
31	1 PC REAR STAY ARM RH <i>Best</i>	181.00 <i>2</i>	
32	1 PC REAR CROSSMEMBER RH <i>Neu</i>	867.60 <i>1</i>	
	<i>1 pc front door RH ✓</i>	11.867.80	
	Less 20%	2.373.56	9,494.24
	Special Net		
33	1 SET REAR DOOR TRIM CLIPS RH <i>Neu</i>	60.00 30	
34	1 PC REAR WINDSCREEN INNER SEAL RUBBER <i>Neu</i>	60.00 40	
35	1 PC REAR WINDSCREEN SEALANT <i>Neu</i>	60.00 ✓	
36	1 SET REAR RH FENDER COWLING CLIPS <i>Neu</i>	60.00 30	
37	1 SET REAR BUMPER CLIPS <i>Neu</i>	40.00 30	
38	1 PC REAR TYRE RH <i>Punctured.</i>	380.00 180 <i>180</i>	
		660.00	660.00
	Labour		
39	1 TO CHECK WIRING	50.00 30	
40	1 (REAR) TO REMOVE AND REFIT WINDSCREEN GLASS	120.00 ✓	
41	1 TO REMOVE AND REFIT SEAT CUSHION & INNER TRIM	200.00 80	
42	1 TO REMOVE AND REFIT REAR DOOR GLASS RH <i>2 Hinges</i>	100.00 80	
43	1 TO REMOVE AND REFIT ANGLE GLASS	80.00 30	
44	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
45	1 TO REMOVE AND REFIT UNDERCARRIAGE	580.00 220	
46	1 (REAR) TO CHECK WHEEL ALIGNMENT	120.00 80	
47	1 TO SPRAY PANEL SEALANT	150.00 60	
48	1 (REAR) TO SPRAY PAINTING	1,400.00 1000	
49	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,000.00 1300	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Estimate No: EST2200259

Date: 12 Aug 2022

Veh Reg No: SLC5736U

Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT

Chasis No: JM6BM42A8G0338826

Reg. Date: 19/05/2016

Your Ref No: YM9043C

Claim Type: Third Party
Accident Date: 11/08/2022
TP Veh Reg No: YM9043C

Estimate Repair Cost to Vehicle No :SLC5736U

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		4.880.00	4.880.00
		Total	S\$ 15,034.24
		Add GST @ 7%	1,052.40
		Total Amount Payable	<u>S\$ 16,086.64</u>

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND EIGHTY SIX AND CENTS SIXTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Adrian Lim
h/c. 15/08/22
10 Days