

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 20 Dec 2022

Preliminary Advice

Vehicle No	: SJQ26T	Accident Date	: 11/08/2022
Make	: LEXUS RX	Policy No.	: DMPCSNW00202242101
Assignment Date	: 15/08/2022	Excess	: S\$750.00
Date of Inspection	: 15/08/2022	Est. Duration of Repair	: 16
Inspection At	: N-51 AUTOMOTIVE PTE LTD (KAKI BUKIT AUTOHUB) (HQ) KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18 SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,367.00
Revised Amount	:S\$	35,741.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	35,741.20
Lump Sum Repair	:S\$	28,600.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	182,000.00
COE / PARF Rebate	:S\$	67,926.00
Salvage Value	:S\$	
Margin for Repair	:S\$	114,074.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON REPAIR COST.