

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM HOCK SENG
BLK 583 WOODLANDS DRIVE 16 #07-464
SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
Date in : 12/08/2022
Vehicle Num. : SJQ26T
Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
Chassis/Eng# : JTJZAMCA302048609/8ARW936420

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
ENGINE LH SIDE UNDER COVER	1	120.00	120.00
ENGINE LH UNDER COVER	1	180.00	180.00
FRONT BONNET	1	1200.00	1,200.00
FRONT BONNET DAMPER L/R	2	160.00	320.00
FRONT BONNET HINGES L/R	2	55.00	110.00
FRONT BONNET INSULATOR MAT	1	260.00	260.00
FRONT BONNET INSULATOR MAT CLIPS	8	3.00	24.00
FRONT BONNET RUBBER SEAL	1	55.00	55.00
FRONT BUMPER	1	420.00	420.00
FRONT BUMPER INNER SPONGE	1	95.00	95.00
FRONT BUMPER LH FOGLAMP	1	330.00	330.00
FRONT BUMPER LH FOGLAMP COVER	1	120.00	120.00
FRONT BUMPER LH FOGLAMP COVER CHROME MOULDING	1	280.00	280.00
FRONT BUMPER LH INNER AIR GUIDE (LOWER)	1	90.00	90.00
FRONT BUMPER LH INNER AIR GUIDE (TOP)	1	90.00	90.00
FRONT BUMPER LH SIDE COVER	1	60.00	60.00
FRONT BUMPER LH SIDE LOWER LID GARNISH	1	250.00	250.00
FRONT BUMPER LOWER CENTER LID GARNISH	1	180.00	180.00

*** This is a computer-generated document which requires no signature.***

WUJI AUTOMOTIVE PTE LTD
Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM HOCK SENG
BLK 583 WOODLANDS DRIVE 16 #07-464
SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
Date in : 12/08/2022
Vehicle Num. : SJQ26T
Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT BUMPER LOWER GRILLE	1	320.00	320.00
FRONT BUMPER LOWER GRILLE CHROME MOULDING	1	330.00	330.00
FRONT BUMPER LOWER GRILLE LH COVER	1	35.00	35.00
FRONT BUMPER LOWER UNDER COVER	1	200.00	200.00
FRONT BUMPER PARKING SENSOR	2	210.00	420.00
FRONT BUMPER PARKING SENSOR 'O' RING	2	28.00	56.00
FRONT BUMPER PARKING SENSOR HOLDER BRACKET	4	28.00	112.00
FRONT BUMPER PARKING SENSOR WIRE HARNESS	1	380.00	380.00
FRONT BUMPER REINFORCEMENT	1	270.00	270.00
FRONT BUMPER SIDE RETAINER L/R	2	58.00	116.00
FRONT ENGINE CROSS MEMBER	1	1600.00	1,600.00
FRONT ENGINE CROSS MEMBER BRACKET LH (FRONT)	1	160.00	160.00
FRONT ENGINE CROSS MEMBER BRACKET LH (REAR)	1	160.00	160.00
FRONT ENGINE CROSS MEMBER MOUNTING (FRONT)	2	100.00	200.00
FRONT ENGINE CROSS MEMBER MOUNTING (REAR)	2	100.00	200.00
FRONT GRILLE	1	760.00	760.00
FRONT GRILLE 'LOGO' EMBLEM	1	180.00	180.00
FRONT GRILLE CHROME MOULDING	1	370.00	370.00

*** This is a computer-generated document which requires no signature.***

W-S-T AUTOMOTIVE PTE LTD
Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM HOCK SENG
BLK 583 WOODLANDS DRIVE 16 #07-464
SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
Date in : 12/08/2022
Vehicle Num. : SJQ26T
Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT GRILLE UPPER RUBBER SEAL	1	78.00	78.00
FRONT GRILLE UPPER TOP COVER	1	175.00	175.00
FRONT HEADLAMP L/R	2	1550.00	3,100.00
FRONT HEADLAMP PANEL	1	650.00	650.00
FRONT LH ABS SENSOR	1	210.00	210.00
FRONT LH AUTO COOLER	1	450.00	450.00
FRONT LH AUTO COOLER AIR DUCT	1	180.00	180.00
FRONT LH AUTO COOLER BRACKET	1	200.00	200.00
FRONT LH CONVERTER UNIT	1	850.00	850.00
FRONT LH DOOR	1	560.00	560.00
FRONT LH DOOR FRAME STICKER (NO:1)	1	60.00	60.00
FRONT LH DOOR FRAME STICKER (NO:2)	1	60.00	60.00
FRONT LH DOOR FRAME STICKER (NO:3)	1	60.00	60.00
FRONT LH DOOR PROTECTOR GARNISH	1	200.00	200.00
FRONT LH DOOR UPPER MOULDING RIVET	8	3.00	24.00
FRONT LH DOOR VERTICAL GARNISH	1	120.00	120.00
FRONT LH DOOR WEATHER STRIP SEAL	1	105.00	105.00
FRONT LH DRIVE SHAFT	1	820.00	820.00

*** This is a computer-generated document which requires no signature.***

W-S-T AUTOMOTIVE PTE LTD
Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM HOCK SENG
BLK 583 WOODLANDS DRIVE 16 #07-464
SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
Date in : 12/08/2022
Vehicle Num. : SJQ26T
Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH FENDER	1	440.00	440.00
FRONT LH FENDER ARCH GARNISH	1	185.00	185.00
FRONT LH FENDER INNER COVER	1	75.00	75.00
FRONT LH FENDER INNER PANEL	1	370.00	370.00
FRONT LH FENDER INNER PANEL TOP COVER	1	180.00	180.00
FRONT LH FENDER INNER SHIELD	1	200.00	200.00
FRONT LH FENDER QUARTER GARNISH	1	75.00	75.00
FRONT LH FENDER SIDE BRACKET	1	65.00	65.00
FRONT LH FENDER WHEEL HOUSE	1	420.00	420.00
FRONT LH FUSE BOX CASING	1	380.00	380.00
FRONT LH FUSE BOX TRAY	1	200.00	200.00
FRONT LH FUSE BOX WIRE HARNESS ASSY	1	2900.00	2,900.00
FRONT LH HEADLAMP CONTROL UNIT	1	480.00	480.00
FRONT LH KNUCKLE ARM	1	350.00	350.00
FRONT LH KNUCKLE ARM BEARING	1	110.00	110.00
FRONT LH LINKAGE	1	80.00	80.00
FRONT LH LOWER ARM	1	240.00	240.00
FRONT LH LOWER ARM BALL JOINT	1	125.00	125.00

*** This is a computer-generated document which requires no signature.***

WUJI AUTOMOTIVE PTE LTD
Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM HOCK SENG
BLK 583 WOODLANDS DRIVE 16 #07-464
SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
Date in : 12/08/2022
Vehicle Num. : SJQ26T
Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH SHOCK ABSORBER	1	300.00	300.00
FRONT LH SHOCK ABSORBER MOUNTING	1	100.00	100.00
FRONT LH SHOCK ABSORBER MOUNTING BEARING	1	80.00	80.00
FRONT LH SHOCK ABSORBER MOUNTING RUBBER	1	60.00	60.00
FRONT LH SHOCK ABSORBER MOUNTING SPONGE	1	70.00	70.00
FRONT LH SPORT RIM	1	2500.00	2,500.00
FRONT LH STEERING TIE ROD END	1	105.00	105.00
FRONT LH WHEEL HUB	1	330.00	330.00
FRONT LH WIPER BLADE	1	85.00	85.00
FRONT STABILIZER BAR	1	320.00	320.00
FRONT STEERING RACK & PINION	1	1800.00	1,800.00
FRONT WINDSCREEN GLASS	1	1050.00	1,050.00
FRONT WINDSCREEN GLASS SEAL	1	75.00	75.00
FRONT WINDSCREEN GLASS SIDE MOULDING L/R	2	85.00	170.00
FRONT WIPER GRILLE GARNISH	1	290.00	290.00
REAR LH DOOR	1	750.00	750.00
REAR LH DOOR ARCH GARNISH	1	95.00	95.00
REAR LH DOOR ARCH RUBBER SEAL	1	105.00	105.00

*** This is a computer-generated document which requires no signature.***


N51 AUTOMOTIVE PTE LTD
 Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
 Date in : 12/08/2022
 Vehicle Num. : SJQ26T
 Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
 Chassis/Eng# : JTJZAMCA302048609/8ARW936420

REAR LH DOOR FRAME STICKER (NO:1)	1	57.00	57.00
REAR LH DOOR FRAME STICKER (NO:2)	1	57.00	57.00
REAR LH DOOR FRAME STICKER (NO:3)	1	57.00	57.00
REAR LH DOOR INNER TRIM BOARD	1	900.00	900.00
REAR LH DOOR PROTECTOR GARNISH	1	220.00	220.00
REAR LH DOOR UPPER MOULDING RIVET	7	3.00	21.00
REAR LH DOOR VERTICAL GARNISH	1	120.00	120.00
REAR LH DOOR WEATHER STRIP	1	110.00	110.00
REAR LH SPORT RIM	1	2500.00	2,500.00
REAR LH WHEEL BEARING	1	360.00	360.00
Subtotal before discount			37,517.00
Percentage discount 0%			0.00
Sub-total 1			37,517.00
AUTO OIL	1	200.00	200.00
BATTERY ASSY	1	250.00	250.00
FRONT GRILLE UPPER TOP COVER CLIPS - SET	1	50.00	50.00
FRONT LH DOOR PROTECTOR GARNISH CLIPS - SET	1	50.00	50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET	1	40.00	40.00

*** This is a computer-generated document which requires no signature.***

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
 Date in : 12/08/2022
 Vehicle Num. : SJQ26T
 Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
 Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	50.00
FRONT LH TYRE	1	350.00	350.00
FRONT WINDSCREEN GLASS E.R.P BRACKET	1	25.00	25.00
FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER	1	15.00	15.00
FRONT WINDSCREEN GLASS SEALANT	1	80.00	80.00
REAR LH DOOR ARCH GARNISH CLIPS - SET	1	20.00	20.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	50.00
REAR LH DOOR PROTECTOR GARNISH CLIPS - SET	1	50.00	50.00
REAR LH TYRE	1	350.00	350.00
Subtotal before discount			1,580.00
Percentage discount 0%			0.00
Sub-total 2			1,580.00
Parts-total			39,097.00

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	150.00
To reset system after repair works	280.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	400.00
To remove, change windscreen.	150.00
To remove, install engine with transmission. (to FR)	400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
 Date in : 12/08/2022
 Vehicle Num. : SJQ26T
 Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
 Chassis/Eng# : JTJZAMCA302048609/8ARW936420

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	400.00
To remove, reinstall rear suspension and undercarriage part. (to FR)	150.00
To road test driving, check and resetting wheel alignments system.	100.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	160.00
To remove, reinstall dashboard fascia, meter reading and etc. (to FR)	280.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,800.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,000.00
Labour Total	6,270.00
Parts & Labour Total	45,367.00

*** This is a computer-generated document which requires no signature.***