

# 51. AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOODLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

## TAX INVOICE

OD Chinn.

Repair Code : CLM17327

Date in : 12/08/2022

Xinn Chinn.

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIV

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
ENGINE LH SIDE UNDER COVER <i>{ Dehd</i>	1	120.00	✓ 120.00
ENGINE LH UNDER COVER	1	180.00	✓ 180.00
FRONT BONNET <i>Dented.</i>	1	1200.00	✓ 1,200.00
FRONT BONNET DAMPER L/R <i>HE m</i>	2	160.00	✗ <del>320.00</del>
FRONT BONNET HINGES L/R <i>Bent.</i>	2	55.00	✗ <del>110.00</del>
FRONT BONNET INSULATOR MAT <i>{ Not nec</i>	1	260.00	✗ <del>260.00</del>
FRONT BONNET INSULATOR MAT CLIPS	8	3.00	✗ <del>24.00</del>
FRONT BONNET RUBBER SEAL <i>new</i>	1	55.00	✓ 55.00
FRONT BUMPER <i>Distorted</i>	1	420.00	✓ 420.00
FRONT BUMPER INNER SPONGE <i>crushed</i>	1	95.00	✓ 95.00
FRONT BUMPER LH FOGLAMP	1	330.00	✓ 330.00
FRONT BUMPER LH FOGLAMP COVER <i>{ missing</i>	1	120.00	✓ 120.00
FRONT BUMPER LH FOGLAMP COVER CHROME MOULDING <i>missing</i>	1	280.00	✓ 280.00
FRONT BUMPER LH INNER AIR GUIDE (LOWER) <i>{ crushed</i>	1	90.00	✓ 90.00
FRONT BUMPER LH INNER AIR GUIDE (TOP)	1	90.00	✓ 90.00
FRONT BUMPER LH SIDE COVER <i>Distorted</i>	1	60.00	✓ 60.00
FRONT BUMPER LH SIDE LOWER LID GARNISH <i>{ Distorted</i>	1	250.00	✓ 250.00
FRONT BUMPER LOWER CENTER LID GARNISH	1	180.00	✓ 180.00

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOODLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

**TAX INVOICE**

Repair Code : CLM17327  
 Date in : 12/08/2022  
 Vehicle Num. : SJQ26T  
 Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE  
 Chassis/Eng# : JTJZAMCA302048609/8ARW936420

Description	Qty	Unit Price	Total Price	Remarks
FRONT BUMPER LOWER GRILLE	1	320.00	320.00	crushed
FRONT BUMPER LOWER GRILLE CHROME MOULDING	1	330.00	330.00	crushed
FRONT BUMPER LOWER GRILLE LH COVER	1	35.00	35.00	crushed
FRONT BUMPER LOWER UNDER COVER	1	200.00	200.00	to be replaced
FRONT BUMPER PARKING SENSOR	2	210.00	420.00	1 piece missing, 1 piece damaged
FRONT BUMPER PARKING SENSOR 'O' RING	2	28.00	56.00	new
FRONT BUMPER PARKING SENSOR HOLDER BRACKET	4	28.00	112.00	new
FRONT BUMPER PARKING SENSOR WIRE HARNESS	1	380.00	380.00	wire snapped
FRONT BUMPER REINFORCEMENT	1	270.00	270.00	new
FRONT BUMPER SIDE RETAINER L/R	2	58.00	116.00	kit 2nd
FRONT ENGINE CROSS MEMBER	1	1600.00	1600.00	to be replaced
FRONT ENGINE CROSS MEMBER BRACKET LH (FRONT)	1	160.00	160.00	to be replaced
FRONT ENGINE CROSS MEMBER BRACKET LH (REAR)	1	160.00	160.00	to be replaced
FRONT ENGINE CROSS MEMBER MOUNTING (FRONT)	2	100.00	200.00	new
FRONT ENGINE CROSS MEMBER MOUNTING (REAR)	2	100.00	200.00	new
FRONT GRILLE	1	760.00	760.00	crushed
FRONT GRILLE 'LOGO' EMBLEM	1	180.00	180.00	new
FRONT GRILLE CHROME MOULDING	1	370.00	370.00	crushed

Air Cleaner Box

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOOLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

**TAX INVOICE**

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT GRILLE UPPER RUBBER SEAL	<i>None</i>	1	78.00	X	<del>78.00</del>
FRONT GRILLE UPPER TOP COVER	<i>None</i>	1	175.00	X	<del>175.00</del>
FRONT HEADLAMP L/R	<i>LH cracked, RH cracked</i>	2	1550.00	<del>1550.00</del>	<i>3110.00</i>
FRONT HEADLAMP PANEL	<i>Distorted</i>	1	650.00	✓	650.00
FRONT LH ABS SENSOR	<i>None</i>	1	210.00	X	<del>210.00</del>
FRONT LH AUTO COOLER	<i>Distorted</i>	1	450.00	✓	450.00
FRONT LH AUTO COOLER AIR DUCT	<i>Distorted</i>	1	180.00	✓	180.00
FRONT LH AUTO COOLER BRACKET	<i>Best</i>	1	200.00	✓	200.00
FRONT LH CONVERTER UNIT	<i>Distorted</i>	1	850.00	X	<del>850.00</del>
FRONT LH DOOR	<i>Repair</i>	1	560.00	+	560.00
FRONT LH DOOR FRAME STICKER (NO:1)	} <i>Not All</i>	1	60.00	+	60.00
FRONT LH DOOR FRAME STICKER (NO:2)		1	60.00	+	60.00
FRONT LH DOOR FRAME STICKER (NO:3)		1	60.00	+	60.00
FRONT LH DOOR PROTECTOR GARNISH		1	200.00	+	200.00
FRONT LH DOOR UPPER MOULDING RIVET		8	3.00	+	24.00
FRONT LH DOOR VERTICAL GARNISH	1	120.00	+	120.00	
FRONT LH DOOR WEATHER STRIP SEAL	1	105.00	+	105.00	
FRONT LH DRIVE SHAFT	<i>Best</i>	1	820.00	✓	820.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n5.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOODLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

### TAX INVOICE

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH FENDER	<i>Distorted</i>	1	440.00	✓	440.00
FRONT LH FENDER ARCH GARNISH	<i>Missing</i>	1	185.00	✓	185.00
FRONT LH FENDER INNER COVER	<i>Wear</i>	1	75.00	✗	75.00
FRONT LH FENDER INNER PANEL	<i>Peeps</i>	1	370.00	✗	370.00
FRONT LH FENDER INNER PANEL TOP COVER	<i>Delcd</i>	1	180.00	✓	180.00
FRONT LH FENDER INNER SHIELD	<i>lon.</i>	1	200.00	✓	200.00
FRONT LH FENDER QUARTER GARNISH	<i>Wear</i>	1	75.00	✗	75.00
FRONT LH FENDER SIDE BRACKET	<i>Beut.</i>	1	65.00	✓	65.00
FRONT LH FENDER WHEEL HOUSE	<i>Distorted</i>	1	420.00	✓	420.00
FRONT LH FUSE BOX CASING	<i>Wt</i>	1	380.00	✓	380.00
FRONT LH FUSE BOX TRAY	<i>Cracked</i>	1	200.00	✓	200.00
FRONT LH FUSE BOX WIRE HARNESS ASSY	<i>Wear Snapped</i>	1	2900.00	✗	2,900.00
FRONT LH HEADLAMP CONTROL UNIT	<i>Distd</i>	1	480.00	✓	480.00
FRONT LH KNUCKLE ARM	<i>Distd</i>	1	350.00	✓	350.00
FRONT LH KNUCKLE ARM BEARING	<i>Distd</i>	1	110.00	✓	110.00
FRONT LH LINKAGE	<i>Beut</i>	1	80.00	✓	80.00
FRONT LH LOWER ARM	<i>Beut</i>	1	240.00	✓	240.00
FRONT LH LOWER ARM BALL JOINT	<i>Distd</i>	1	125.00	✓	125.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOODLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

**TAX INVOICE**

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIV.

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH SHOCK ABSORBER	<i>Best</i>	1	300.00	<input checked="" type="checkbox"/>	300.00
FRONT LH SHOCK ABSORBER MOUNTING		1	100.00	<input checked="" type="checkbox"/>	100.00
FRONT LH SHOCK ABSORBER MOUNTING BEARING	} <i>HL per</i>	1	80.00	<input checked="" type="checkbox"/>	80.00
FRONT LH SHOCK ABSORBER MOUNTING RUBBER		1	60.00	<input checked="" type="checkbox"/>	60.00
FRONT LH SHOCK ABSORBER MOUNTING SPONGE		1	70.00	<input checked="" type="checkbox"/>	70.00
FRONT LH SPORT RIM		<i>lit.</i>	1	2500.00	<input checked="" type="checkbox"/>
FRONT LH STEERING TIE ROD END	<i>New</i>	1	105.00	<input checked="" type="checkbox"/>	105.00
FRONT LH WHEEL HUB	<i>Buyd</i>	1	330.00	<input checked="" type="checkbox"/>	330.00
FRONT LH WIPER BLADE	<i>HL</i>	1	85.00	<input checked="" type="checkbox"/>	85.00
FRONT STABILIZER BAR	<i>New</i>	1	320.00	<input checked="" type="checkbox"/>	320.00
FRONT STEERING RACK & PINION	<i>New</i>	1	1800.00	<input checked="" type="checkbox"/>	1800.00
FRONT WINDSCREEN GLASS	<i>crackd</i>	1	1050.00	<input checked="" type="checkbox"/>	1050.00
FRONT WINDSCREEN GLASS SEAL	<i>New</i>	1	75.00	<input checked="" type="checkbox"/>	75.00
FRONT WINDSCREEN GLASS SIDE MOULDING L/R	<i>HL</i>	2	85.00	<input checked="" type="checkbox"/>	170.00
FRONT WIPER GRILLE GARNISH	<i>lit</i>	1	290.00	<input checked="" type="checkbox"/>	290.00
REAR LH DOOR	<i>Deited</i>	1	750.00	<input checked="" type="checkbox"/>	750.00
REAR LH DOOR ARCH GARNISH	<i>HL</i>	1	95.00	<input checked="" type="checkbox"/>	95.00
REAR LH DOOR ARCH RUBBER SEAL	<i>HL</i>	1	105.00	<input checked="" type="checkbox"/>	105.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOODLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

**TAX INVOICE**

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

REAR LH DOOR FRAME STICKER (NO:1)	1	57.00	57.00
REAR LH DOOR FRAME STICKER (NO:2)	1	57.00	57.00
REAR LH DOOR FRAME STICKER (NO:3)	1	57.00	57.00
REAR LH DOOR INNER TRIM BOARD	1	900.00	900.00
REAR LH DOOR PROTECTOR GARNISH	1	220.00	220.00
REAR LH DOOR UPPER MOULDING RIVET	7	3.00	21.00
REAR LH DOOR VERTICAL GARNISH	1	120.00	120.00
REAR LH DOOR WEATHER STRIP	1	110.00	110.00
REAR LH SPORT RIM	1	2500.00	2500.00
REAR LH WHEEL BEARING	1	360.00	360.00
Subtotal before discount			37,517.00
Percentage discount 0%			0.00
Sub-total 1			37,517.00
AUTO OIL	1	200.00	200.00
BATTERY ASSY	1	250.00	250.00
FRONT GRILLE UPPER TOP COVER CLIPS - SET	1	50.00	50.00
FRONT LH DOOR PROTECTOR GARNISH CLIPS - SET	1	50.00	50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET	1	40.00	40.00

Handwritten calculations:  
 29682.20  
 + (15) 2968.20  
 -----  
 32650.20

Handwritten totals:  
 28692  
 31561.20

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOODLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

**TAX INVOICE**

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH FENDER INNER SHIELD CLIPS - SET	<i>new</i>	1	50.00	<i>30</i> <del>50.00</del>
FRONT LH TYRE	<i>at</i>	1	350.00	<i>300</i> <del>350.00</del>
FRONT WINDSCREEN GLASS E.R.P BRACKET		1	25.00	<i>✓</i> 25.00
FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER	<i>gone</i>	1	15.00	<i>✓</i> 15.00
FRONT WINDSCREEN GLASS SEALANT	<i>new</i>	1	80.00	<i>60</i> <del>80.00</del>
REAR LH DOOR ARCH GARNISH CLIPS - SET	<i>new</i>	1	20.00	<i>✓</i> 20.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	<i>+</i> 50.00
REAR LH DOOR PROTECTOR GARNISH CLIPS - SET	<i>new</i>	1	50.00	<i>30</i> <del>50.00</del>
REAR LH TYRE	<i>at new</i>	1	350.00	<i>X</i> 350.00
			Subtotal before discount	<i>530</i> 1,580.00
Percentage discount 0%				0.00
			<b>Sub-total 2</b>	1,580.00
			<b>Parts-total</b>	<b>39,097.00</b>

**LABOUR**

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

To remove, change windscreen.

To remove, install engine with transmission. (to FR)

*120 ✓ ? 150*  
*180 ~~200~~*  
*100 ~~300~~*  
*120 150*  
*X ~~400~~*

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

LIM HOCK SENG  
 BLK 583 WOODLANDS DRIVE 16 #07-464  
 SINGAPORE 730583

Contact : 96669980

**TAX INVOICE**

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIV

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	<del>320</del> 300.0
To remove, re-inst. ll rear suspension and undercarriage part. (to FR)	X 150.0
To road test driving, check and resetting wheel alignments system.	80 100.0
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80 160.0
To remove, reinstall dashboard fascia, meter reading and etc. (to FR)	X 280.0
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1200 1800.0
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1400 2,000.0
<b>Labour Total</b>	3640 6,270.0
<b>Parts &amp; Labour Total</b>	45,367.0

3600

\*\*\* This is a computer-generated document which requires no signature.\*\*\*  
 page 8

Adrian Li  
 I/S NE Autohub  
 15/08/22  
 Excom \$750.

36820.20  
 - 21) 7364.04  
 -----  
 29456.16

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Revised  
 Adrian Li  
 31/08/22  
 Total: 35741.20  
 C/S : 28.6k

28.6k