

Not Authorized
 U/Sing @13,800/2
 Recovery After Paint



Ho Wee Lam
 Blk 96 #12-30 Lorong 3 Toa Payoh
 Singapore 310096

41 days

File No :
 Date : 12-August-2022

Estimated cost of repair for vehicle no : SLG6339E Honda Vezel
 Accident involving vehicle no: SLG6339E & SLR2981T on 08.08.2022

Description	Quantity	Cost Price
Bonnet	1	\$ B 450.00 —
RH bonnet hinge	1	\$ D1 38.00 —
LH bonnet hinge	1	\$ D1 38.00 —
Bonnet lock	1	\$ B1 90.00 —
RH bonnet inner rubber seal	1	\$ M 25.00 —
LH bonnet inner rubber seal	1	\$ M 25.00 —
RH bonnet inner centre seal	1	\$ M 25.00 —
LH bonnet inner centre seal	1	\$ M 25.00 —
RH head lamp	1	\$ M/C/M 1,050.00 —
LH head lamp	1	\$ M 1,050.00 —
RH head lamp bracket	1	\$ CM 30.00 —
LH head lamp bracket	1	\$ CM 30.00 —
Front grille	1	\$ CM 360.00 —
Front grille clips (1 set)	1	\$ M 12.00 —
Front grille emblem	1	\$ M 28.00 —
Front grille chrome moulding centre	1	\$ CM 280.00 —
Front grille centre upper bracket	1	\$ CM 58.00 —
RH Front grille bracket	1	\$ CM 20.00 —
LH Front grille bracket	1	\$ CM 20.00 —
RH Front grille chrome moulding	1	\$ CM 55.00 —
LH Front grille chrome moulding	1	\$ CM 55.00 —
Front bumper	1	\$ B 450.00 —
Front bumper clips (1 set)	1	\$ M 15.00 —
Front bumper centre grille	1	\$ S 55.00 X
Front bumper reinforcement	1	\$ B 260.00 —
RH Front bumper retainer	1	\$ D1 20.00 —
LH Front bumper retainer	1	\$ D1 20.00 —
RH Front bumper daytime LED lamp	1	\$ S 380.00 X
LH Front bumper daytime LED lamp	1	\$ S 380.00 X
RH Front bumper daytime LED lamp cover	1	\$ S 60.00 X
LH Front bumper daytime LED lamp cover	1	\$ S 60.00 X
Front bumper lower spoiler	1	\$ S 280.00 X
RH Front bumper retainer	1	\$ Repainted 20.00 X
LH Front bumper retainer	1	\$ M 20.00 X
RH Front bumper bracket	1	\$ R 35.00 X
LH Front bumper bracket	1	\$ R 35.00 X
RH front fender	1	\$ B 220.00 —
LH front fender	1	\$ R 220.00 X

RH front fender badge "hybrid"	1	\$	Na	55.00	—
LH front fender badge "hybrid"	1	\$	Na	55.00	—
Front support panel	1	\$	By	380.00	✓
Front support panel top garnish	1	\$	CM	65.00	✓
Front support panel top garnish clips (1 set)	1	\$	Na	18.00	✓
Air con condensor	1	\$	B1	380.00	✓
Air con condensor pipe inlet	1	\$	Pa	130.00	X
Air con condensor pipe outlet	1	\$	Pa	160.00	X
RH Air con condensor air guide	1	\$	CM	40.00	✓
LH Air con condensor air guide	1	\$	Pa	40.00	X
Air con condensor fan cowling	1	\$	CM	110.00	✓
Air con condensor fan blade	1	\$	Pa	280.00	X
Air con condensor fan motor	1	\$	Di	65.00	✓
Radiator	1	\$	Pa	750.00	✓
Radiator top hose	1	\$	Pa	25.00	X
Radiator lower hose	1	\$	Pa	30.00	X
Radiator auto fan cowling	1	\$	CM	120.00	✓
Radiator auto fan blade	1	\$	Pa	60.00	X
Radiator auto fan motor	1	\$	Pa	280.00	✓
Radiator spare tank	1	\$	Di	45.00	✓
Engine air cleaner air duct	1	\$	ERA	60.00	✓
Wiper water tank	1	\$	Di	70.00	✓
Rear tailgate	1	\$	Pa	680.00	✓
Rear tailgate emblem	1	\$	Pa	28.00	X
Rear tailgate moulding	1	\$	Pa	160.00	X
Rear tailgate badge "Vezel"	1	\$	Na	45.00	—
Rear tailgate badge "RS"	1	\$	Na	45.00	—
Rear tailgate badge "hybrid"	1	\$	Na	48.00	—
Rear tailgate inner lock	1	\$	Pa	90.00	—
Rear tailgate inner trim board	1	\$	Di/HT	150.00	✓
Rear tailgate weatherstrip	1	\$	Pa	70.00	X
RH Rear tailgate inner taillamp	1	\$	Pa	320.00	X
LH Rear tailgate inner taillamp	1	\$	Pa	320.00	X
Rear windscreen moulding	1	\$	Na	85.00	✓
RH outer tail lamp	1	\$	Pa	330.00	X
LH outer tail lamp	1	\$	Pa	330.00	X
Rear bumper	1	\$	B1	580.00	✓
Rear bumper clips (1 set)	1	\$	Na	15.00	—
RH Rear bumper retainer	1	\$	Pa	20.00	X
LH Rear bumper retainer	1	\$	Pa	20.00	X
RH Rear bumper reflector	1	\$	Pa	60.00	X
LH Rear bumper reflector	1	\$	Pa	60.00	X
Rear end panel	1	\$	B1	360.00	✓

Rear end panel top trim	1		\$	<i>Rd</i> 70.00	<i>?</i>
Rear floor panel	1		\$	<i>R</i> 650.00	<i>X</i>
Rear floor panel top trim board	1		\$	<i>Sw</i> 360.00	<i>?</i>
			\$	14,408.00	
		Add 15%	\$	2,161.20	
			\$	16,569.20	
Front number plate	1	S. nett	\$	<i>Sw</i> 45.00	<i>X</i>
Engine coolant	1	S. nett	\$	<i>M</i> 30.00	<i>✓</i>
Rear windscreen sealant	1	S. nett	\$	<i>M</i> 60.00	<i>405M</i>
Rear windscreen inner seal	1	S. nett	\$	<i>M</i> 28.00	<i>—</i>
Rear parking sensors (1 set)	1	S. nett	\$	<i>CMA</i> 260.00	<i>2005M</i>
Rear number plate	1	S. nett	\$	<i>M</i> 45.00	<i>X</i>
To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality					
			\$	120.00	<i>100d</i>
To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment					
			\$	850.00	<i>600d</i>
To spray paint affected front and inner damaged portion inclusive of preparatory works and material					
			\$	1,100.00	<i>1000d</i>
To apply anti-corrosion Tuff-Kote on front portion					
			\$	100.00	<i>9d</i>
To remove and reinstall rear windscreen and conduct water leak test.					
			\$	120.00	<i>✓</i>
To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member, to replace damaged parts and adjust rear body and tailgate alignment					
			\$	1,200.00	<i>700d</i>
To spray paint affected rear and inner damaged portion inclusive of preparatory works and material					
			\$	850.00	<i>800d</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality					
			\$	80.00	<i>40d</i>

To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes

\$ *nn* 150.00 *X*

To apply anti-corrosion Tuff-Kote on rear portion

\$ 100.00 *601*

\$ 21,707.20

T/Party: India International Insurance Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ho Wee Lam
Blk 96 #12-30 Lorong 3 Toa Payoh
Singapore 310096

Date : 22-August-2022

Supplementary estimated cost of repair for vehicle no: **SLG6339E** Honda Vezel
Accident involving vehicle no: **SLG6339E & SLR2981T** on **08.08.2022**

Description	Quantity	Cost Price
Front radar <i>1200</i>		<i>mbim</i> \$ 1,650.00 ✓
Front radar bracket <i>R1 300.00</i>		\$ <i>R</i> 550.00 ✓
Front bumper reinforcement nitrogen bar		\$ <i>R R</i> 350.00 ✗
Rear end pael nitrogen bar		\$ <i>R</i> 580.00 ✓
		\$ 3,130.00
	Add 15%	\$ 469.50
		<u>\$ 3,599.50</u>

To recalibrate radar

\$ 580 *2 for*