

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 03/08/2022

Estimated repair cost for vehicle no : SLF4539M HONDA VEZEL 1.5X CVT

CHASSIS: RU11113420 (2016)

03/08/2022

TP Allianz

Xiao Tony

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Rehd</i>	\$872.00	\$872.00 ✓
2	1	FRONT BUMPER REINFORCEMENT <i>Neu</i>	\$560.00	\$560.00 +
3	1	FRONT BUMPER REINFORCEMENT GARNISH LH <i>Neu</i>	\$56.00	\$56.00 +
4	1	FRONT BUMPER SIDE RETAINER LH <i>Rehd</i>	\$24.00	\$24.00 ✓
5	1	FRONT BUMPER TOW COVER <i>Neu</i>	\$42.00	\$42.00 +
6	1	FRONT BUMPER LOWER LIP <i>bon</i>	\$462.00	\$462.00 386
7	1	FRONT BUMPER LOWER LIP RUBBER <i>Neu</i>	\$126.00	\$126.00 +
8	1	FRONT BUMPER UNDER COVER GARNISH <i>Neu</i>	\$106.00	\$106.00 +
9	1	FRONT BUMPER LOWER GRILLE <i>Neu</i>	\$210.00	\$210.00 +
10	1	FRONT BUMPER FOG LAMP LH <i>Neu</i>	\$362.00	\$362.00 +
11	1	FRONT BUMPER FOG LAMP OUTER GARNISH LH <i>Neu</i>	\$162.00	\$162.00 +
12	1	FRONT BUMPER FOG LAMP BRACKET LH <i>Neu</i>	\$98.00	\$98.00 +
13	1	FRONT SUPPORT PANEL TOP GARNISH RH <i>Neu</i>	\$112.00	\$112.00 +
14	1	FRONT SUPPORT PANEL SIDE GARNISH RH <i>Neu</i>	\$84.00	\$84.00 +
15	1	FRONT HEADLAMP LH <i>Rehd</i>	\$1,999.00	\$1,999.00 1784
16	1	FRONT HEADLAMP LOWER BRACKET LH <i>Neu</i>	\$56.00	\$56.00 +
17	1	FRONT HEADLAMP WIRE HARNESS <i>Neu</i>	\$711.30	\$711.30 +
18	1	FRONT FENDER RH <i>Neu</i>	\$389.00	\$389.00 +
19	1	FRONT FENDER OUTER GARNISH LH <i>Neu</i>	\$183.60	\$183.60 ✓
20	1	FRONT FENDER INNER SHIELD RH <i>Rehd</i>	\$113.00	\$113.00 ✓
21	1	FRONT LOWER ARM LH <i>Neu</i>	\$654.50	\$654.50 +
22	1	FRONT SHOCK ABSORBER LH <i>Neu</i>	\$389.60	\$389.60 +
23	1	FRONT KNUCKLER ARM LH <i>Neu</i>	\$489.10	\$489.10 +
24	1	FRONT KNUCKLER ARM BEARING LH <i>Neu</i>	\$215.60	\$215.60 +

TOTAL : \$8,476.70

LESS 20 % \$1,695.34

SUB-TOTAL : \$6,781.36

3362.60

2690.08

SLF4539M HONDA VEZEL

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>pc</i>	\$80.00	\$80.00 <i>30</i>
2	1	FRONT FENDER INNER COWLING CLIPS <i>pc</i>	\$50.00	\$50.00 <i>20</i>
3	1	FRONT FENDER OUTER GARNISH CLIPS <i>pc</i>	\$20.00	\$20.00 ✓
4	1	FRONT SPORT RIM RH <i>set</i>	\$650.00	\$650.00 <i>4w</i>
5	1	FRONT TYRE RH <i>pc</i>	\$280.00	\$280.00 <i>x</i>

470

TOTAL: \$1,080.00

TOTAL PARTS: \$7,861.36

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE
- 6 TO CONDUCT WHEEL ALIGNMENT

400 \$1,500.00
250 \$1,200.00
30 \$80.00
760 + \$300.00
 + \$200.00
80 \$150.00

Subtotal :- \$3,430.00

Total:- \$11,291.36

Adrian Lij
H/S. 17/08/22
03 Rys

total: 392008
H/S: 3.1K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: