

Case Details

Case Reference Number : TAX/07/22/2082
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4907Y

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-18910-ID
Assigned By : Tan Lee Ge #

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 25/07/2022 11:45 PM
Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair	R
Standard	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	R
Standard	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	Not Give	Xan
Standard	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	Xan
Standard	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	see
Standard	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	0	0	Not Give	Xan
Standard	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	Xan
Standard	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	Xan
Standard	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, FRONT FENDER TO COWL SIDE LH	1	15.20	15.20	25.00	11.40	Replace	0	0	Not Give	Xan
Standard	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	Xan

Total Spare Part Cost 2,160.64

Surveyor Total 850.68

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 1,698.94

Final Sur Total 680.54

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	676.00	200	
Total:			676.00	200.00 /	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			756.00	400.00 /	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 Xan	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 Xan	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0 Xan	
Total:			380.00	40.00 /	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,698.94	680.54
Total Labour Cost	676.00	200.00
Total Spray Painting	756.00	400.00
Other	380.00	40.00
Overall Total	3,510.94	1,320.54
Lump Sum Repair Option	☐	☒
Lump Sum Total	3,500.00	1,300.00
Surveyor Approved Amount		1,300.00
No of Repair Days*	4	2

Estimator Assessment(\$)	Surveyor Assessment(\$)
Remarks	LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO.
Surveyor Name	Rasul
Signature	
Survey Date	05/08/2022
Save Clear	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: