



**Section A - Accident Details**

Registration Number	SHC4907Y
Case Reference Number	TAX/07/22/2082
Registration Date	5/2/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIANG ENG HUAT
Type of Accident	Side Swipe
Accident Date and Time	26/7/2022 7:45 AM
Accident Reported Date and Time	26/7/2022 9:09 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115719
Special Instruction to ARC, if any	TP/ AIG - LKK
Prepared Date and Time	27/7/2022 11:34 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$1,728.51	\$680.54
Total Other Cost	\$380.00	\$40.00
<b>TOTAL COST</b>	<b>\$3,540.51</b>	<b>\$1,320.54</b>
<b>Lump Sum Total</b>	<b>\$3,550.00</b>	<b>\$1,300.00 (L/S)</b>
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	San Wei Lau	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	05/08/2022 3:51 PM	05/08/2022 2:38 PM
Signature		
Remarks		LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO.

**Section C - Quotation and Accident Invoice Details**

Quotation Number	QN-2208-0159	Invoice Number	
Quotation Date	12.08.2022	Invoice Date	
Invoice Amount		Prepared Date	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$676.00	\$200.00 ✓
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$756.00</b>	<b>\$400.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00 NN
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00 NN
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 NN
<b>Total Other Costs</b>	<b>\$380.00</b>	<b>\$40.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
		53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given
		53867-47030	SEAL, FRONT FENDER TO COWL SIDE LH	0.00	\$15.20	0.00	\$0.00	Replace	Not Given
		53852-47020	FENDER LINER PAD, FR WHEEL. LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given
<b>Total</b>					<b>\$2,677.31</b>		<b>\$850.68</b>		

R  
R  
X NN  
X NN  
✓ SCR  
X NN  
X NN  
X NN  
X NN  
X NN  
X NN

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	850.68	
	-20%	
	680.54	L/S \$1,300/-
+	200.00	
+	440.00	
	1,320.54	