



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303817

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 16/06/2023  
Reference CC6/CTI22007777/Uya3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SKS 7311B  
Insured Veh. PC 9164X  
Claim No. SNM22D205744/C02  
Policy No. DMB15NW00007932200  
Accident Date 11/08/2022  
Inspection Date 16/08/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                           |                 | Ref: CC6/CTI22007777/Uya3q2<br>Date: 16/06/2023<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                 |                                                              |  |
| Insured Veh.                                                                                                                           | PC 9164X                                                                                  | Veh. Inspected  | SKS 7311B                                                    |  |
| Policy No.                                                                                                                             | DMB15NW00007932200                                                                        | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM22D205744/C02                                                                          | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                           | Assign Date     | 16/08/2022                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                 |                                                              |  |
| Make & Model                                                                                                                           | TOYOTA ALPHARD (A)                                                                        | c.c             | 2362                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.    | 2015                                                         |  |
| Chassis No.                                                                                                                            | JTEGD21H708355053                                                                         | Colour          | WHITE                                                        |  |
| Odometer                                                                                                                               | 201932 KM                                                                                 | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                  | Modification    | SPORTS RIM                                                   |  |
| General                                                                                                                                | GOOD                                                                                      |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                      | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 215/60 R17                                                                                | MICHELIN        | 6 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 215/60 R17                                                                                | MICHELIN        | 6 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 215/60 R17                                                                                | MICHELIN        | 6 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 215/60 R17                                                                                | MICHELIN        | 6 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                           |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                 |                                                              |  |
| Accident Date                                                                                                                          | 11/08/2022                                                                                | Inspection Date | 16/08/2022                                                   |  |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                           |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                           | 5 Working Days  |                                                              |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 7311B

| Qty | Description of Parts                | Condition                               | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------|-----------------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                                         |                           |                   |
| 1   | REAR WINDSCREEN                     | NOT NECESSARY                           | 1,866.10                  | -                 |
| 1   | REAR WINDSCREEN MOULDING            | NECESSARY                               | 199.50                    | 166.10            |
| 1   | TAILGATE                            | BADLY DENTED                            | 2,650.20                  | 1,915.30          |
| 1   | TAILGATE 'ALPHARD' EMBLEM           | NECESSARY                               | 105.10                    | 82.00             |
| 1   | TAILGATE REAR LOGO                  | NECESSARY                               | 68.50                     | 68.50             |
| 1   | TAILGATE WEATHERSTRIP               | TWISTED                                 | 488.90                    | 399.50            |
| 1   | TAILGATE INNER LOCK                 | DENTED / SHORTED                        | 650.20                    | 509.10            |
| 1   | TAILGATE INNER TRIM BOARD           | DEFORMED / TORN                         | 955.80                    | 745.20            |
| 1   | SET TAILGATE INNER TRIM BOARD CLIPS | NECESSARY                               | 50.00                     | 50.00             |
| 2   | TAILGATE REFLECTORS @\$689.10       | CRACKED                                 | 1,378.20                  | 1,160.20          |
| 1   | TAILGATE OUTER GARNISH              | CRACKED                                 | 1,855.20                  | 1,105.30          |
| 1   | REAR BUMPER                         | DISTORTED                               | 1,850.00                  | 799.20            |
| 2   | REAR BUMPER SIDE RETAINERS @\$85.00 | N/S BENT                                | 170.00                    | 85.00             |
| 1   | SET REAR BUMPER CLIPS               | NECESSARY                               | 50.00                     | 50.00             |
| 1   | REAR BUMPER TOW COVER               | DEFORMED                                | 48.00                     | 48.00             |
| 2   | REAR BUMPER PDC SENSORS @\$465.00   | SHORTED                                 | 930.00                    | 618.00            |
| 2   | REAR BUMPER REFLECTORS @\$98.00     | NOT NECESSARY                           | 196.00                    | -                 |
| 1   | REAR END PANEL                      | BADLY DENTED                            | 911.20                    | 755.10            |
| 1   | REAR END PANEL TOP GARNISH          | TWISTED                                 | 245.20                    | 245.20            |
| 2   | TAILLAMPS @\$950.10                 | NOT NECESSARY                           | 1,900.20                  | -                 |
| 2   | TAILLAMP LOWER GARNISHS @\$650.10   | N/S DEFORMED / O/S TO REPAIR SEE LABOUR | 1,300.20                  | 520.00            |
| 1   | REAR ANTENNA SENSOR                 | CRACKED                                 | 226.20                    | 185.20            |
| 1   | REAR BUZZER SENSOR                  | NOT FITTED                              | 210.50                    | -                 |
| 1   | REAR FENDER INNER TRIM BOARD N/S    | DEFORMED / TORN                         | 1,125.50                  | 845.00            |
| 1   | REAR SPARE TYRE BRACKET             | BENT                                    | 399.10                    | 320.00            |
|     | LESS 25% DISCOUNT                   |                                         | -                         | -2,667.98         |
|     |                                     |                                         | 19,829.80                 | 8,003.92          |

Report Ref No. CC6/CTI22007777/Uya3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                           | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | <b><u>SPECIAL NETT ITEMS</u></b>                                                               |               |                           |                   |
| 1                                                                           | REAR WINDSCREEN SEALANT (SN)                                                                   | NECESSARY     | 50.00                     | 40.00             |
| 1                                                                           | REAR WINDSCREEN INNER SEAL (SN)                                                                | NECESSARY     | 50.00                     | 40.00             |
| 1                                                                           | REAR LICENCE PLATE (SN)                                                                        | NOT NECESSARY | 50.00                     | -                 |
| 1                                                                           | REAR END PANEL SEALANT (SN)                                                                    | NECESSARY     | 50.00                     | 50.00             |
|                                                                             |                                                                                                |               | 200.00                    | 130.00            |
|                                                                             | <b><u>LABOUR</u></b>                                                                           |               |                           |                   |
|                                                                             | TO CHECK WIRING.                                                                               |               | 50.00                     | 20.00             |
|                                                                             | TO DISMANTLE & REPLACED REAR PDC SENSOR.                                                       |               | 80.00                     | 50.00             |
|                                                                             | TO DISMANTLE & REFIX REAR WINDSCREEN.                                                          |               | 150.00                    | 120.00            |
|                                                                             | TO DISMANTLE & REFIX TAILGATE MECHANISM.                                                       |               | 100.00                    | 60.00             |
|                                                                             | TO DISMANTLE & REFIX CUSHION UPHOLSTERY.                                                       |               | 150.00                    | 80.00             |
|                                                                             | TO SPRAY RUST PROOFING.                                                                        |               | 100.00                    | 60.00             |
|                                                                             | TO RESET & REPROGRAMME SYSTEM.                                                                 | NOT NECESSARY | 150.00                    | -                 |
|                                                                             | LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP LOWER GARNISHS. |               | 1,200.00                  | 800.00            |
|                                                                             | TO PUTTY & SPRAY PAINTING.                                                                     |               | 1,500.00                  | 1,000.00          |
|                                                                             |                                                                                                |               | 3,480.00                  | 2,190.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                |               | <b>23,509.80</b>          | <b>10,323.92</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                |               |                           | <b>8,200.00</b>   |

Report Ref No. CC6/CTI22007777/Uya3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKS 7311B

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 7311B

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 7311B

RE-INSPECTION

