

ASS. REC. BY:

REF: C12/ 220077811ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.1.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBB 2852 Yr Regn: 08, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS NV200 c.c. 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 26758 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1YAA M20 80002102Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NIS / S/Rim / STD A/Rim orTyre Size: F: 165/60R14
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 24/7/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/8 83725.31 Cnfw

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

) \$ + RS. \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Not Authorised

Recovery B4 paint

4 days

83.72531

Vehicle Insured : GZ 8855 C
Accident Date : 24-Jul-2022

No. : 32483

Date : 11-Aug-2022

Our Ref : 022167 (CHINA) / SANDRA

PAGE : 1

U-GOLD SERVICES
Singapore

ESTIMATED COST OF REPAIR FOR NISSAN NV200 1.6A (1598CC)(2021) GBB2852K

1 pc tailgate	2135.60	At/war	2,175.80	n	✓
1 pc tailgate logo			157.00	n	✓
1 pc tailgate 'NV200' emblem			71.40	n	✓
1 pc tailgate 'VANETTE' emblem			71.40	n	✓
1 pc rear bumper	481.00		539.90	n	✓
2 pcs rear bumper side retainer LH/RH		@ S\$ 40.70	81.40	n	✓
8 pcs rear bumper clip		@ S\$ 6.10	48.80	n	✓
1 pc rear end panel			168.00	n	X
			3,313.70		
		Less 10% :	-331.37		
			2,982.33		
1 pc tailgate '70KM/H' sticker			15.00	sn	✓
1 pc tailgate '6PAX' sticker			15.00	sn	✓
1 pc tailgate glass sealant			40.00	sn	✓
1 pc tailgate glass damping seal			20.00	sn	✓
1 pc reverse sensor assy			220.00	sn	X
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.			680.00	4001	
To remove and refit reverse sensor assy.			60.00	501	
To remove and refit rear windscreen glass and conduct water leak test			120.00	✓	

, any key to continue...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : GZ 8855 C

Our Ref : 022167

Page : 2

No. : 32483

To transfer tailgate's fittings

601
80.00

To putty and respray on affected
portions.

3001
680.00

Total : S\$ 4,912.33

Singapore Dollars FOUR THOUSAND NINE HUNDRED
TWELVE AND CENTS THIRTY THREE Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: