

ASS. REC. BY:

REF:

C721 220077831Kc

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5331 B Yr Regn: 06.21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius C.C. 1788Colour: M.P. White / Red A/C: Insured / Std / NI / NASp. Reading: 84310 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU203092337Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: Wanli 195/65R15R: Pailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 30/6/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/8 8:14 24.60 Cohn

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) S + RS. \$

) Fuel

) Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

Not Authorized
Repair By paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5331B

AAD2205-084

1424.60

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 AUG 2022

SHC5331B

JTDKB3FU203092337

200303878K

TOYOTA

PRIUS GEN 4

15/05/2022

SLC9321G/ China

30/06/2021

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 COVER, REAR BUMPER, LOWER
- 1 PANEL SUB-ASSY, BODY LOWER BACK

LIST

\$	Bu	485.60	✓
\$	Bu	332.70	✓
\$	Not for	374.50	✓
\$	Pu	118.30	X
\$	Pu	132.60	X
\$	Pu	118.30	X
\$	Pu	132.60	X
\$	Pu	22.00	X
\$	Pu	651.00	X

TOTAL	\$	2,367.60
25%	\$	591.90
	\$	1,775.70

Special Nett

- 1 REAR BUMPER SIDE CLIP
- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER RETAINER CLIP

\$	na	60.00	✓
\$	Pu	700.00	X
\$	na	85.00	X
\$	na	75.00	X

TOTAL	\$	920.00
--------------	-----------	---------------

TOTAL PARTS	\$	2,695.70
--------------------	-----------	-----------------

LABOUR

- To Rust-Proofing and apply undercoat Of The Affected Areas. \$ na 240.00 X
- To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ na 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2205-084**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5331B

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	2001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	4 170.00	X
TOTAL	\$	5,100.00	
Over All Total	\$	7,795.70	

(PART-BY-PART) Repair Days~~20~~ Days

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: