

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5436H*Not Notion
Penny B4 paint**2798.73*

AAD2208-059

Vehicle No.:
Chassis No.:
Co UEN:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

15 AUG 2022**SHC5436H**

JTDKB3FU803092472

200303878K

TOYOTA

PRIUS GEN 4

11/08/2022

GBH7135H/AIG

13/09/2021

PART**LIST**

1	COVER, REAR BUMPER	\$	Bu/No	485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	Bu	332.70	✓
1	GUARD, REAR BUMPER, CENTER	\$	Bu	374.50	✓
1	SEAL, REAR BUMPER SIDE, RH	\$	Sn	118.30	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	Sn	132.60	X
1	COVER, REAR BUMPER, LOWER	\$	Sn	22.00	✓
1	COVER, DECK TRIM, REAR	\$	Sn	126.70	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	Sn	651.00	X
1	REFLECTOR ASSY, REFLEX, RH	\$	Sn	39.00	X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	Sn	241.90	X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	Sn	175.10	X
1	COVER, REAR FLOOR (CTR)	\$	CM	229.90	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	Sn	1,147.80	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	Sn	54.60	—
1	PLATE, BACK DOOR NAME, NO.1	\$	Sn	54.60	—
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	Sn	47.90	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	my CM	913.60	✓
1	BOARD ASSY, BACK DOOR TRIM	\$	Sn	259.20	X
1	WEATHERSTRIP, BACK DOOR	\$	Sn	372.30	X
1	STAY ASSY, BACK DOOR, LH	\$	Sn	242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	Sn	242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	Sn	61.00	✓
1	HINGE ASSY, BACK DOOR, RH	\$	Sn	61.00	X

TOTAL \$ 6,386.30**25% \$ 1,596.58****\$ 4,789.73****Special Nett**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2208-059

SHC5436H

- 1 REAR BUMPER SIDE CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER RETAINER CLIP

\$	nn	60.00	X
\$	nn	100.00	305nl
\$	nn	100.00	305nl
\$	Ad	700.00	2205nl
\$	nn	85.00	605nl
\$	nn	75.00	X
TOTAL	\$	1,120.00	
TOTAL PARTS	\$	5,909.73	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	2001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	4401
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$	4	170.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	4	170.00	X
TOTAL	\$		5,100.00	

Over All Total \$ 11,009.73**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(PART-BY-PART) Repair Days**20 Days****2 days**