

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	06/08/2022
Vehicle Reg. No.:	SMR460G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	OPEL ASTRA, 1.4 J (A)	Vehicle Reg. Date:	16/12/2019
Vehicle Colour:	GREY		
Engine No:	A2191579L8GX0009	Chassis No:	W0VBD8EG3K8058051
Odometer:	133498 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	525.36
Miscellaneous Items	0.00
Labour	350.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	875.36
- Excess (S\$)	2,000.00
Nett Amount (S\$)	-1,124.64

This claim is handled by: TAN CHIN CHINGenerated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2022)

Parts: 144 OPEL ASTRA 1.4 J (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SMR460G/24/08/2022 17:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39158021	*DAYTIME CONTROL UNIT dented	0.00	0.00	*455.20 F 569
2	1	39086891	*BRACKET BUMPER SIDE LH distorted SVC	0.00	0.00	*22.40 F
F=Franchise part.						
Sub Total (S\$)						477.60
+ Margin on L,N Items 10.00% (S\$)						47.76
Total Parts (S\$)						525.36

Munich Autocare Pte Ltd/SMR460G/24/08/2022 17:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REFIX, REPAIR, KNOCKING WELDING FRONT SUPPORT, CHASSIS LH & DAMAGED AREAS	New	350.00 X
Gross Labour Cost (S\$)			350.00

Munich Autocare Pte Ltd/SMR460G/24/08/2022 17:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >