



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22007790/Uvy3e2	
			Date: 24/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 508Y	Veh. Inspected	Q 69M
	Policy No.	D22MTPCVE001249	Coverage (\$)	0.00
	Claim No.	CMTD2202757/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	16/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VELLFIRE (A)	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	AGH300124185	Colour	BLACK
	Odometer	60957 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/35 R19	PIRELLI	5 mm
	L/H Front Tyre	255/35 R19	PIRELLI	5 mm
	R/H Rear Tyre	255/35 R19	PIRELLI	5 mm
	L/H Rear Tyre	255/35 R19	PIRELLI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/08/2022	Inspection Date	16/08/2022
	Survey held at	15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre		
	Repairer	2ND AUTO		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	