

Vehicle Damage Assessment Report for [SHA7995H]

Estimate Created: 12/01/2023 09:11 by Insurlogic 5 (Insurlogic_Pte_Ltd)

Owned: 12/01/2023 09:40 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Ioniq
Engine Type			
License Plate Number	SHA7995H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$11,692.00 WITH 7 DAYS

Insurlogic 5 (12/01/2023 09:40)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BONNET		1	2253.80	-20.00 %	1,803.04
BONNET LOCK		1	127.30	-20.00 %	101.84
RADIATOR GRILLE NEW MODEL		1	1568.60	-20.00 %	1,254.88
FRONT BUMPER COVER		1	481.10	-20.00 %	384.88
FRONT BUMPER SPONGE		1	186.90	-20.00 %	149.52
FRONT BUMPER REINFORCEMENT		1	1136.70	-20.00 %	909.36
FRONT BUMPER MOULDING CENTRE UPPER		1	368.50	-20.00 %	294.80
FRONT BUMPER BRACKET TOP (RH)		1	35.00	-20.00 %	28.00
FRONT BUMPER BRACKET (RH)		1	28.00	-20.00 %	22.40
FRONT BUMPER CLIPS		1	25.00	-20.00 %	20.00
FRONT BUMPER GRILLE (RH)		1	186.90	-20.00 %	149.52
DAY LIGHT, RH		1	642.50	-20.00 %	514.00
HEADLAMP SUPPORT PANEL ASSY		1	1139.30	-20.00 %	911.44
HEADLAMP RH		1	2110.30	-20.00 %	1,688.24
RADIATOR INVERTER		1	884.80	-20.00 %	707.84
RADIATOR		1	710.50	-20.00 %	568.40
FRONT PILLAR UPPER COVER - OUTER RH		1	89.60	-20.00 %	71.68
FRONT FENDER (RH)		1	490.70	-20.00 %	392.56
WIPER CONTAINER ASSY		1	385.40	-20.00 %	308.32
EMBLEM - BLUE DRIVE		1	26.60	-20.00 %	21.28

Parts Subtotal 10,302.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	600.00	0.00 %	600.00
WIRING CHARGE	RnR	30.00	0.00 %	30.00
TUFF KOTE	RnR	30.00	0.00 %	30.00
REMOVE/REFIX RADIATOR	RnR	50.00	0.00 %	50.00
REMOVE/REFIX AIRCON & REFILL GAS	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING CHARGE	Full spray	600.00	0.00 %	600.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	790.00
			Paint Labor Subtotal	600.00
			Labor Subtotal	1,390.00

Summary

Repair Cost	11,692.00
Discount(0 %)	(0.00)
	11,692.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	11,692.00