

ASS. REC. BY: Taufik

REF:

NS/ INC 22007793/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBC 5849K**

Policy No. _____


Claims No. **MT/1185278-002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **WP**Date: _____ Person Contacted: Chang Vehicle: IN / OUTVeh No: SH7760B Yr Regn: 2016 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai 140 C.C. 1685Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RMH4LB414MG4087920

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westeche

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 31/7/2022 D.O.I. 10/8/22Survey held at Confert Bay

Des. of Damages: Frt / Rear / O/S / N/S / U/C + Rooftop: or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/9/22 Taufikh informed LS \$6450 (Red 6867.37, 51%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 28/9/22-typist

Rep. Format: **TP**Lump Sum / L.S. (\$) **\$6450**Days Of Repair: **6**Resurvey No. of Trip: **1**Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

REPAIR ESTIMATE*

10.08.2022

MODEL **HYU- I40**

CHIANG/NTUC

- * To provide fair book value
- * To check upper limit of fair

Date/Time: 10.08.2022 08:27

Page : 1

eam: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4522866

JC N05525863

USTOMER

3/MS COMFORT TRANSPORTATION PTE LTD

USTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

L. (R) 65508755 (O)
(P)

SCOUNT CARD NO.

REGN NO:
SH 7760B

MILEAGE

MAKE:
HYUNDAI

FUEL
E.....1/2.....F

MODEL I-40 08.08.2022 08:36

DATE/TIME IN

YR OF MANU.
12.05.2016

TARGET DATE

CHASSIS CODE
KMHLB41UMGU087920


COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 10.08.2022

ATURE: TP/3P 31.07.2022

/NO LABOR CODE DESCRIPTION



HECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

Vehicle No.: SH 7760B CHIANG

Vehicle No.: SH 7760B

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard